

**HARFORD COUNTY PUBLIC SCHOOLS
REQUEST FOR PROPOSALS FOR
HAZARDOUS MATERIAL VERIFICATION AND REMOVAL
SPECIFICATION PREPARATION SERVICES**

AUGUST 17, 2017

HAVRE DE GRACE HIGH SCHOOL / HAVRE DE GRACE MIDDLE SCHOOL

Scope of Service:

Harford County Public Schools (HCPS) has a need to acquire consultant services to conduct a survey and determine the extent of existing hazardous materials at the Havre de Grace High School building and site in preparation for the demolition of that facility for future site-related field and parking improvements.

HCPS also has a need to acquire consultant services to conduct a survey and determine the extent of existing hazardous materials at the Havre de Grace Middle School building and site in preparation for the demolition of that facility for future site-related field and parking improvements.

HCPS is, by this Request for Proposal (RFP), soliciting pricing from consultants for the building and site survey described above and as further defined below.

The hazardous materials referred to herein shall include:

1. Asbestos containing materials
2. Lead
3. PCBs
4. Contaminated soils
5. Mercury
6. CFC's
7. Any other material which is required by law to be removed and disposed as a hazardous material

The services the Consultant shall provide under this RFP shall include:

1. Review of drawings, specifications and other pertinent documents relating to the construction of the building and site to be surveyed.
2. Perform destructive and nondestructive testing and inspection as required to determine the extent of the hazardous materials defined above in this RFP.

3. Collect and test samples (PLM and TEM) as required to determine hazardous material content. Materials to be inspected and tested shall include but not be limited to:
 - a) Building, pipe and duct insulation including pipe/duct concealed by walls or ceilings
 - b) Waterproofing and damp proofing materials on building foundations and within exterior cavity walls
 - c) Interior and exterior joint sealants
 - d) Interior and exterior glazing compounds
 - e) Mastic behind chalkboards, tackboards, etc.
 - f) Interior and exterior plaster, transite, etc.
 - g) Interior and exterior painted surfaces
 - h) Glazed CMU
 - i) Interior/exterior electrical fixtures, transformers, etc.
 - j) Interior floor, wall and ceiling finishes
 - k) Roofing materials and roof insulation
 - l) Ceramic tile
4. Perform lead infiltration testing to discern whether lead containing materials may be crushed and used as fill or disposed as common waste.
5. If masonry with asbestos mastic is found, request reclassification of masonry with asbestos mastic to allow disposal as common waste, not as hazmat. This will include coordination with HCPS, Environmental Protection Agency (EPA) and MDE as necessary.
6. Document in a detailed report the results of the testing and inspection to include the types of hazardous materials encountered and the general location(s) where they were found.
7. Provide a complete set of bid documents to include drawings and specifications for the removal of all hazardous materials from the building(s) and site. HCPS and Grimm + Parker Architects will include these bid documents in the overall bid documents for the demolition of the building(s) and subsequent site improvement construction.

The subject high school is comprised of two (2) separate buildings that contain approximately 144,815 GSF of space. Removal of all hazardous materials is planned as a part of the demolition process. Consultants shall review this RFP document and submit proposals as specified herein. Copies of the HCPS AHERA management plan are attached to this RFP for your use and information during proposal preparation.

The subject middle school is approximately 102,000 GSF of space. Removal of all hazardous materials is planned as a part of the demolition process. Consultants shall review this RFP document and submit proposals as specified herein. Copies of the HCPS AHERA management plan are attached to this RFP for your use and information during proposal preparation.

Consultants shall review this RFP, the buildings(s), the site and the AHERA management plan in preparing pricing for the services described elsewhere in this RFP. Consultants shall provide pricing on the enclosed proposal form for HCPS consideration in the award of services.

Consultants shall provide a list of five (5) similar projects performed by their firm and the individual(s) that will be assigned to this survey project. Consultants shall submit proof of staff certification for the handling of hazardous materials in the State of Maryland. Certification verification should include the AHERA Building Inspector Course and AHERA Management Planner status as these apply to proposed staff. Licensed asbestos inspectors will conduct a survey of the building materials suspected to contain asbestos. The survey will be conducted in accordance with Occupational Safety and Health Administration requirements and EPA, AHERA guidelines for the locations and number of samples to be collected.

The work to be performed under this RFP shall be performed all at one time. Please note: all buildings will be occupied during testing. Any required destructive testing needs to be repaired for safety. The survey testing and inspection work required to be performed in the building(s) and on the site shall commence on September 1, 2017 and shall be 100% complete on or before September 22, 2017. Resulting reports shall be provided to HCPS on or before September 30, 2017. The required bid documents shall be provided to HCPS on or before September 30, 2017.

Consultant Service RFP responses shall be delivered to the HCPS Planning and Construction Department located at 102 South Hickory Avenue Bel Air, Maryland 21014, no later than NOON (Local Time) on Wednesday, August 30, 2017.

Havre de Grace High School / Havre de Grace Middle School
Asbestos Containing Material (HAZARDOUS MATERIAL)
Survey/Verification/Specification Preparation
Request for Proposal
August 17, 2017
Page 4

FAXED PROPOSALS WILL NOT BE ACCEPTED.

All proposals shall be directed to:

Mr. Harry Miller
Assistant Supervisor
Harford County Public Schools
Planning & Construction Department
102 South Hickory Avenue
Bel Air, Maryland 21014
Telephone (410) 809-6120

PROPOSALS must be received at the address listed above by:

AUGUST 30, 2017
12:00 NOON LOCAL TIME
NO EXCEPTIONS

CONSULTANT PRICING FORM

Havre de Grace High School Site Survey/Verification
Including document review _____

Havre de Grace High School
Associated Testing/ PLM/Unit _____
Sample Analysis

TEM/Unit _____

Havre de Grace High School
Total Sampling Cost Projection _____

Havre de Grace High School Specification Preparation _____

Havre de Grace Middle School Site Survey/Verification
Including document review _____

Havre de Grace Middle School
Associated Testing/ PLM/Unit _____
Sample Analysis

TEM/Unit _____

Havre de Grace Middle School
Total Sampling Cost Projection _____

Havre de Grace Middle Specification Preparation _____

Total Havre de Grace High School
and Havre de Grace Middle School _____

***** Consultants should provide an estimate of total testing/analysis costs based on a review of existing HCPS documents and a site tour. This estimate will be used to establish a reimbursable allowance for testing/analysis.

***** RFP responses are due in the Office of Planning and Construction at 102 South Hickory Avenue Bel Air, Maryland 21014 Noon on Wednesday, August 30, 2017.



**August 2016 - AHERA 3-Year
Re-Inspection Report**

Hayre De Grace Middle School
401 Lewis Lane
Hayre De Grace, MD 21078

Prepared for:

Hartford County Public Schools
102 South Hickory Avenue
Bel Air, MD 21014

Prepared by:

SSM Group, Inc.
1047 North Park Road
Reading, PA 19610
SSM Project No. 100368.0001

Management Plan updated by:

A handwritten signature in black ink, appearing to read "W. Kafinowsky", written over a horizontal line.

William M. Kafinowsky
State of Maryland
Inspector/Management Planner
(#130311)

**HARFORD COUNTY PUBLIC SCHOOLS
HAVRE DE GRACE MIDDLE SCHOOL
AHERA 3-YEAR RE-INSPECTION REPORT
AUGUST, 2016**

EXECUTIVE SUMMARY

The AHERA 3-Year Re-inspection of the Havre De Grace Middle School was conducted by Mr. William M. Katinowsky on August 2, 2016. Mr. Katinowsky is an EPA AHERA accredited Building Inspector/Management Planner, who is also licensed in the same capacity by the Maryland Department of the Environment (MDE). The re-inspection was performed in accordance with EPA 40 CFR, Part 763, which is commonly referred to as AHERA.

During the re-inspection, Mr. Katinowsky identified and assessed the condition and quantity of all known ACM, as noted in the previous re-inspection. Locations, quantities and assessment conditions are noted on the Room-by-Room Inventory of ACM included with this report. There were no damaged or significantly damaged materials found during this inspection.

ADDITIONAL MATERIAL(S) ADDED

Stage light wire insulation was assumed during this re-inspection.

MATERIALS ADDED DURING THE 2013 INSPECTION

During the 2013 AHERA 3-year re-inspection cove base and cove base adhesive was added. Most of these materials were replacement materials of original materials and were non-asbestos containing materials. SSM recommends that since these materials were added as assumed to contain asbestos, they continue to be monitored and sampled prior to removal or renovation of the materials. SSM recommends bulk sampling only if these materials will be removed/impacted during future renovations.

BULK SAMPLING

No bulk samples were collected during this re-inspection.

RESPONSE ACTIONS

No known response actions were taken since the previous re-inspection.

CONCLUSION

Floor tile and associated mastic, fitting insulation and widow glazing remain in the building. There are several areas where the floor tile is slightly damaged. Also, two (2) sections of damaged fittings were discovered in the Custodial Office. SSM recommends that you monitor the condition of the materials and repair/ remove as needed. Continue to handle all ACM and assumed ACM in accordance with your current Operations and Maintenance (O&M) Plan. We also remind you to continue to provide maintenance and custodial staff with annual asbestos awareness training, continue to provide annual notification to building staff, parents and guardians, and to assure that copies of all inspection reports and AHERA documentation are maintained in your central AHERA files (located in the Maintenance Facility) and at each individual school (main office in a location that is easily accessible by office staff).

Section 4-1: Material Summary and Estimated Cost of Removal for the Havre De Grace Middle School

| <u>Material & Location</u> | <u>Type</u> | <u>Quantity</u> | <u>Estimated Cost of Removal</u> |
|---------------------------------------|--------------------|------------------------|---|
| Throughout the Building | | | |
| Floor Tile and Mastic | M | 20,000 S.F. | \$80,000 |
| Fitting Insulation | T | 410 Ea. | \$10,300 |
| Exterior Window Glazing | M | 500 L.F. | \$3,000 |

M- Miscellaneous ACM

L.F.= Linear Feet

S.F.= Square Feet

Section 6-1: Recommended Minimum Response Actions for the Havre De Grace Middle School

| <u>Material & Location</u> | <u>Quantity</u> | <u>Response Action</u> |
|---------------------------------------|------------------------|-------------------------------|
| Throughout the Building | | |
| Floor Tile and Mastic | 20,000 S.F. | Handle Under the O&M Program |
| Fitting Insulation | 410 Ea. | Handle Under the O&M Program |
| Exterior Window Glazing | 500 L.F. | Handle Under the O&M Program |

M- Miscellaneous ACM

L.F.= Linear Feet

S.F.= Square Feet

Algorithm Values

ALGORITHM VALUES - SHORT FORM

- Damaged Condition (DC) - 0 Intact, Encapsulated
1 Intact, Minor Water Stain
2 Intact, Cover Poor, Moderate Stain, No Damage
3 Minor Damage, Scrapes, etc., Duct Tape Repair
5 Damage, Fix with Patch, Repair and Encapsulate
7 Significant Damage, Some Removal Needed
10 Very Significant Damage, Removal Mandated
- Exposure Factor (E) - 0 Inaccessible or Non-friable
1 Very Limited Access
2 Maintenance Area Like Boiler Room or Above 2x4's
3 Public Area, 10 Feet and Higher
4 Public Area, 10 Feet and Lower
- Activity Level (AT) - 0 Behind Walls, Locked Closet, etc.
1 Low or Medium Usage (1-3 Persons, 8 Hr/Day)
2 #1 with Vibration or Public Area
4 High Activity (Gym, Loading Dock) and/or High Vibration
- Air Flow Factor (AF) - 0 No Impingement, Little or No Air Flow
1 Low Air Flow or Air Velocity, No Impingement
2 Air Stains, Moderate Velocity, Piston Effect
4 High Air Velocity, Air Erosion
- Potential Damage (PD) - 0 No ACM
1 ACM, No Potential Damage
2 Possible Potential Damage
3 Potential Damage Expected
4 Possible Significant Potential Damage
5 Significant Potential Damage Expected
- Friability (F) - 1 Non-Friable, Behind Walls, etc.
2 Encapsulated, Ceiling Tile, Hard Surface
3 Friable - Standard ACM and Fittings
5 Highly Friable - Delaminating, "Fluffy" Fireproofing
- Percent Asbestos (PA) - 0 = No ACM
1 = >1% but <25% - Chrysotile Only
2 = 25% to 80% - Chrysotile Only
3 = >80% - or any percentage of amosite, crocidolite, anthophyllite, tremolite
or actinolite
- Linear Feet (L) - Refers to quantity of ACM
Square Feet (S) L Linear Feet
S Square Feet

MDE

Asbestos License

William Katinowski
Name


Signature

Inspector/Management Planner Review
Course Title

15024901

Course Date: 12/03/2015
Exp Date: 12/03/2016
Exam Date: 01/07/2016

STATE OF MARYLAND

Allsafe Environmental
Training Provider


375 Kriswell Dr
Address

Boiling Springs, PA 17007
City, State, Zip

717-258-4109
Phone

MDE

Lorraine Anderson
Name of Training Director



For additional information, call MDE (410) 537-3200

Form A: AHERA Three (3) Year (2013) Reinspection Data Summary

| | | | |
|--|--------------------------------------|--|--|
| 1 | Harford County Public Schools | | |
| | LEA Point of Contact: | Cynthia Yost, Environmental Compliance Coordinator | |
| | Facility Number and Name: | | |
| 2 | Facility Address: | Havre De Grace Middle School | |
| | | 7401 Lewis Lane, Havre De Grace, MD 21078-3089 | |
| 3 | Date of Inspection | 8/14/2010 | |
| 4 | EPA Accredited Inspector(s) | Edward Clarke MD # 120333 | |
| | | | |
| | Management Planner(s) | Joseph Williamson MD # 121323 | |
| 5 | 5A | Information provided by HCPS to Meemsco for Review: | |
| | | | |
| | | | Abatement records provided by HCPS are attached |
| | | | |
| | 5B | Comments and Issues: | Mudded fittings in Room J-4 and window glazing at some windows are still present |
| Floor tile and mastic were removed from Room 20 instead of 18 as was reported in the last reinspection report. | | | |
| Assumed Cove base and cove base adhesive glue were found throughout the building. | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| 6 Previously Tested Materials with <u>no asbestos detected (NAD)</u> | | | | | | |
|--|-------------|-------------|----------------------|--------------------------|--|--|
| Homogeneous Material Description | | Location(s) | Sampling Information | | | |
| | | | Samples Adequate? | Samples Collected for HA | | |
| HA ID: | Type: Misc. | | | N/A | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: | Type: Misc. | | | N/A | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: | Type Misc. | | | N/A | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: | Type Misc. | | | N/A | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| | |
|---|--|
| 7 | Description of Asbestos Removal Projects during the last three years, including dates and location of work. |
| X | |
| | January 23, 2012, asbestos containing glue and mastic were removed from behind a 6" wallboard in Room 36. Full containment was utilized. |
| | February 7, 2012, asbestos containing pipe insulation was removed from the hallway between RM 20 and 22. Glovebag methods were utilized. |
| | April 4-5, 2012, asbestos containing window glazing and caulks were removed from hallway by the Media Center. Mini containment was utilized. |
| | June 9, 2011, windows were removed from the 7 th grade hallway. Mini containment was utilized. |
| | July 18-22, 2011, asbestos containment floor tile and mastic were removed from Room #s 22 and 23. Full containment was utilized. |
| | <i>Jun 2013 - floor tile mastic and carpet removed from Media Center using full containment</i> |
| | <i>July 2014 5,365 sqft. tile removed (26, 27, 31, 32 + 33)</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Form A: Homogeneous Area Assessment and Response Action Form

| 8 New suspect ACBM identified during 2013 Re-inspection | | | | | | |
|---|-------------|-------------|----------------------|--------------------------|--|--|
| Homogeneous Material Description | | Location(s) | Sampling Information | | | |
| | | | ACM? | Samples Collected for HA | | |
| HA ID: M001 | Type: Misc. | Throughout | A | | | |
| Detail: 2 x 4 White ceiling tiles | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M002 | Type: Misc. | Throughout | A | | | |
| Detail: 12 x 12 Floor Tiles (Various Colors) | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M003 | Type: Misc. | Throughout | A | | | |
| Detail: Mastic under flooring material | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M004 | Type: Misc. | Throughout | A | | | |
| Detail: Ceramic Tile & Ceramic tile grout | | | | | | |
| | | | | | | |
| | | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| 9 Assessment of Friable and Non-friable Assumed Positive or Tested Positive Materials | | | | | | | |
|---|--|-----|----------|--------------------------------|---------|--|------------------|
| Homogeneous Material Description | Location(s) | ACM | Friable? | Assessment and Response Action | | | |
| | | | | AHERA Assessment Category | | Management Planner's recommended Response Action | |
| | | | | Prior | Current | Action | Notes/Comments |
| HA ID: M001 Type: Misc. Detail 2 x 4 White ceiling tiles | Throughout | A | F | 5 | 5 | O & M | |
| HA ID: M002 Type: Misc. Detail 12 x 12 Floor Tiles (Various Colors) | Throughout | Y | NF | 7 | 7 | AR | |
| HA ID: M003 Type: Misc. Detail: Mastic under flooring material | Throughout | A | NF | 5 | 5 | O & M | |
| HA ID: M004 Type: Misc. Detail: Ceramic Tile & Ceramic tile grout | Throughout | A | F | 5 | 5 | O & M | Grout is Friable |
| Key to Abbreviations: | | | | | | | |
| Type: | TSI= Thermal Systems Insulation, Surf.= Surfacing Material, Misc.= Miscellaneous Material | | | | | | |
| ACM: | A= Assumed, Y= Determined to be asbestos through sampling. | | | | | | |
| Friable | F= Friable, NF= Non-friable. | | | | | | |
| AHERA Assessment Category: | 1)= Damaged or significantly damaged TSI ACBM, 2)= Damaged friable surfacing ACBM, 3)= Significantly damaged friable surfacing ACBM 4)= Damaged or significantly damaged friable miscellaneous ACBM, 5)= ACBM with potential for damage, 6)= ACBM with potential for significant damage 7)= Any remaining friable ACBM or friable suspected ACBM. (8)= Not applicable (non friable surfacing or miscellaneous material). | | | | | | |
| Response Action: | O&M= Continue surveillance and Operations and Maintenance, AR= Abatement Required as soon as possible. | | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| 9 Assessment of Friable and Non-friable Assumed Positive or Tested Positive Materials | | | | | | | | |
|---|--|-----|----------|--------------------------------|---------|--|----------------|---|
| Homogeneous Material Description | Location(s) | ACM | Friable? | Assessment and Response Action | | | | |
| | | | | AHERA Assessment Category | | Management Planner's recommended Response Action | | |
| | | | | Prior | Current | Action | Notes/Comments | |
| HA ID: M005 Type: Misc. Detail Cove Base & Cove Base Adhesive | Throughout | A | NF | 5 | 5 | O & M | | |
| HA ID: M006 Type: Misc. Detail Fire Doors | Throughout | A | NF | N/A | 5 | O & M | | |
| HA ID: Type: Misc. Detail 9" x 9" floor tile | Throughout | | NF | | | | | see 2004 reinspection HGM 1-0928a HGM 1-0928b |
| HA ID: M012 Type: Misc. | | | | | | | | |
| Key to Abbreviations: | | | | | | | | |
| Type: | TSI= Thermal Systems Insulation, Surf.= Surfacing Material, Misc.= Miscellaneous Material | | | | | | | |
| ACM: | A= Assumed, Y= Determined to be asbestos through sampling. | | | | | | | |
| Friable | F= Friable, NF= Non-friable. | | | | | | | |
| AHERA Assessment Category: | 1)= Damaged or significantly damaged TSI ACBM, 2)= Damaged friable surfacing ACBM, 3)= Significantly damaged friable surfacing ACBM 4)= Damaged or significantly damaged friable miscellaneous ACBM, 5)= ACBM with potential for damage, 6)= ACBM with potential for significant damage 7)= Any remaining friable ACBM or friable suspected ACBM. (8)= Not applicable (non friable surfacing or miscellaneous material). | | | | | | | |
| Response Action: | O&M= Continue surveillance and Operations and Maintenance, AR= Abatement Required as soon as possible. | | | | | | | |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace Middle School

ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089

DATE: 7/8/2010

EPA ACCREDITED INSPECTOR/ACCREDITATION NO.: Charles McEleney MD # 106225

SIGNATURE: _____

EPA MANAGEMENT PLANNER/ACCREDITATION NO.: Charles McEleney MD # 106225

SIGNATURE: _____

PREVIOUSLY IDENTIFIED OR ASSUMED ACM:

| | |
|----------------------------------|--|
| Throughout | |
| mud pipe fittings - 410 fittings | |
| 9"x9" floor tile - 20,000 sf | |
| Exterior | |
| window glazing - 500 lf | |
| | |
| | |
| | |
| | |
| | |

CHANGES IN MATERIAL CONDITION:

None

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

Small scale floor tile removal projects have been undertaken since previous AHERA reinspection, including in rooms 18, 20, 28 and 34.

Mud fittings were also identified below the ceiling in closet J-4.

NEWLY IDENTIFIED/SAMPLED MATERIALS:

None glue spots

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace Middle School

ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089

DATE: 7/8/2010

REMAINING ACM IN BUILDING:

Throughout

mud pipe fittings - 410 fittings

9"x9" floor tile - 20,000 sf

5305 SF
639 SF

Exterior

window glazing - 500 lf

mud pipe fittings - good condition

9"x9" floor tile and mastic - good condition

window glazing - good condition

Mud pipe fittings present above metal pan ceiling. Also, below the ceiling in M-2 storage, elec room, S-2, and J-4.

9"x9" floor tile is present throughout. Some tiles around exterior wall are coming up but overall are intact.

Mastic was previously tested to be non-asbestos.

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
BULK SAMPLE DOCUMENTATION**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/8/2010
COLLECTED BY: Charles R. McEleney

| Sample No. | Friable | | Homogeneous Area | Description of Exact Location | Percent Asbestos |
|------------|---------|-----|------------------|-------------------------------|------------------|
| | Yes | No | | | |
| N/A | N/A | N/A | N/A | N/A | N/A |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

NAD = No Asbestos Detected

C&R Environmental Associates, Inc.
1415 Bush Street, 2nd Floor
Baltimore, MD 21230

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/8/2010
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---|-----------------------------|
| Material Type: <u>Mud Pipe Fittings</u> | Location: <u>Throughout</u> |
| Area: _____ Sq. Ft. | Ln. Ft. _____ <u>410</u> |

COMMENTS (Optional)

Mud pipe fittings are present on fiberglass insulated piping. The material is located above the metal pan ceiling throughout the building and below the ceiling in S-2, M-2 Storage Room, the elec room and J-4. Material was observed to be in good condition above missing panels in corridor ceiling.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|-------|
| Significant | _____ |
| Moderate | _____ |
| Light | _____ |
| None | X |

| Water | |
|-----------|-------|
| Extensive | _____ |
| Moderate | _____ |
| Slight | _____ |
| None | X |

| Deterioration | |
|---------------|-------|
| Heavy | _____ |
| Moderate | _____ |
| Light | X |
| None | _____ |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|-------|
| <1 Ft. | _____ |
| 1 to 5 Ft. | _____ |
| Over 5 Ft. | X |

| Accessible | |
|--------------|-------|
| Within Reach | _____ |
| Barely | X |
| Unreachable | _____ |

| Texture | |
|----------|-------|
| Rough | _____ |
| Pitted | _____ |
| Moderate | X |
| Smooth | _____ |

| Adjacent Rooms | |
|----------------|-------|
| Gymnasium | _____ |
| Music Rm. | _____ |
| Mech. Rm. | _____ |
| Elevators | _____ |

AIR FLOW FACTORS

| Barriers | |
|--------------|-------|
| Permanent | _____ |
| Encapsulated | _____ |
| None | _____ |
| Enclosed | X |

| Ventilation | |
|----------------|-------|
| Yes | _____ |
| None | _____ |
| If Yes, Intake | _____ |
| Exhaust | _____ |

| Air Movement | |
|--------------|-------|
| High | _____ |
| Moderate | _____ |
| Low | _____ |

| Air Conduits | |
|--------------|-------|
| Air Plenum | _____ |
| Air Shaft | _____ |
| Elevator | _____ |
| Shaft | _____ |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
REINSPECTION SUMMARY TABLE**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/8/2010

| Homogeneous Area (#), Type of Materials | Sampled 2007 (Y/N) | Friable 2007 (Y/N) | Changes 2010 (Y/N) | Friable 2010 (Y/N) | Sampled 2010 (Y/N) | AHERA Class. | Response Action | Hazard Rank # | Schedule (Initial - Completion) |
|--|--------------------|--------------------|--------------------|--------------------|--------------------|--------------|-----------------|---------------|---------------------------------|
| Mud Pipe Fittings | N | Y | N | Y | N | 5 | O&M | 2 | Ongoing |
| 9"x9" floor tile | N | N | N | N | Y | N/A | O&M | 1 | Ongoing |
| Window Glazing | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

KEY:

Homogeneous Area

T - Thermal System Insulation
 S - Surfacing Material
 M - Miscellaneous

Response Action

RM - Remove
 RP - Repair
 ECP - Encapsulate

O&M - Operations and Maintenance
 ISL - Isolate

C&R Environmental Associates, Inc.
 1415 Bush Street, 2nd Floor
 Baltimore, MD 21230

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
Resource Evaluation**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/8/2010

Costs are projected for removing and for repairing and encapsulating the ACMs assessed during the AHERA Building Re-inspection. The cost estimates are based upon unit cost rates for abatement of various ACMs and are provided for general planning purposes only. Many project-specific factors, including economies of scale, contract and schedule requirements, etc. will affect the actual costs for abatement. The cost estimates provided do not include the cost of replacement of the materials removed or for professional Industrial Hygiene Services, such as project design and air monitoring.

The following pages show response action costs, which are based upon an assessment of the potential health hazard as reflected by the hazard ranking. The hazard ranking system derives from the Hazard Potential Algorithm used by the AHERA Building Inspector to assess the condition of ACM and was approved for use in this reinspection by the Harford County Public Schools AHERA designated person.

Generally, the following Hazard Ranking Values initiate the following actions:

| Hazard Ranking | Response Action |
|----------------|---|
| 6 | Schedule for immediate removal. |
| 5 | Schedule for immediate action (repair/encapsulation or removal). |
| 4 | Monitor. Schedule for near term action. |
| 3 | Monitor. Schedule for future removal. |
| 2 | Monitor. As long as ACM condition does not change or use of area in which ACM exists does not change, schedule for removal later when monies are available. |
| 1 | Monitor. Generally no other action is required unless the building is renovated or demolished. |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update**

**Budgetary Costs by Hazard Ranking
Harford County Public Schools**

| Material | Quantity | Repair/ Encapsulate | Remove |
|---|-----------|------------------------|----------|
| A. Damaged ACM, Hazard Categories 3, 4, 5, 6 | | | |
| <u>Hazard Category 6</u> N/A | | | |
| <u>Hazard Category 5</u> N/A | | | |
| <u>Hazard Category 4</u> N/A | | | |
| <u>Hazard Category 3</u> N/A | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| B. Undamaged ACM, Hazard Categories 1, 2 | | | |
| <u>Hazard Category 2</u> | | | |
| Mud Pipe Fittings | 410 | N/A | \$10,250 |
| <u>Hazard Category 1</u> | | | |
| 9"x9" floor tile | 20,000 sf | N/A | \$70,000 |
| Window glazing | 500 lf | N/A | \$15,000 |
| | | | |
| | | | |
| | | | |
| | | | |

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

CHARLES R. MCELENEY

*has met the attendance requirements and successfully completed
the course entitled*

8-Hr EPA AHERA Insp/Mgmt Planner Refresher

For Accreditation Under TSCA Title II.

2/18/2010

Course Date

2/18/2010

Exam Date

2/18/2011

Expiration Date

ROBERTA SPRATT-RITTER

Principal Instructor



106225

Certification No.

VA106225

Virginia Certification No.

E. RUSH BARNETT

Course Director



1331 Ashton Road

P.O. Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace Middle School

ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089

DATE: 7/20/2007

EPA ACCREDITED INSPECTOR/ACCREDITATION NO.: Charles McEleney MD # 086055

SIGNATURE: *Charles McEleney*

EPA MANAGEMENT PLANNER/ACCREDITATION NO.: Charles McEleney MD # 086055

SIGNATURE: *Charles McEleney*

PREVIOUSLY IDENTIFIED OR ASSUMED ACM:

| | |
|----------------------------------|--|
| Throughout | |
| mud pipe fittings - 410 fittings | |
| 9"x9" floor tile - 20,000 sf | |
| Exterior | |
| window glazing - 500 lf | |
| | |
| | |
| | |
| | |

CHANGES IN MATERIAL CONDITION:

One damaged mud elbow was identified near shelves in Room S-2. *Abatement Report # 14827*
8/20/07 A.I.

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

Small scale projects to remove window glazing have been undertaken since the previous reinspection.

9"x9" floor tile was removed from Room 27 since the previous reinspection.

Mud fittings in the Boys Rest Room of Health Suite were removed since the previous reinspection.

Student laboratory table tops are not suspect ACM. However, some older lab counters are present and may contain asbestos.

NEWLY IDENTIFIED/SAMPLED MATERIALS:

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/20/2007

REMAINING ACM IN BUILDING:

| | |
|----------------------------------|--|
| Throughout | |
| mud pipe fittings - 410 fittings | |
| 9"x9" floor tile - 20,000 sf | |
| Exterior | |
| window glazing - 500 lf | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

mud pipe fittings - good condition
9"x9" floor tile - good condition
window glazing - good condition

Mud pipe fittings present above metal pan ceiling. Also, below the ceiling in M-2 storage, elec room, and S-2.

9"x9" floor tile is present throughout. Some tiles around exterior wall are coming up but overall are intact. Mastic was previously tested to be non-asbestos.

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/20/2007
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---|---|
| Material Type: <u>Mud Pipe Fittings</u> | Location: <u>Throughout</u> |
| Area: Sq. Ft. _____ | Ln. Ft. _____ 410 |

COMMENTS (Optional)

Mud pipe fittings are present on fiberglass insulated piping. The material is located above the metal pan ceiling throughout the building and below the ceiling in S-2, M-2 Storage Room, and the Electrical Room.
One damaged elbow was noted in the S-2 storage room. Damage due to contact with storage items on shelf.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|-------|
| Significant | _____ |
| Moderate | _____ |
| Light | _____ |
| None | X |

| Water | |
|-----------|-------|
| Extensive | _____ |
| Moderate | _____ |
| Slight | _____ |
| None | X |

| Deterioration | |
|---------------|-------|
| Heavy | _____ |
| Moderate | _____ |
| Light | X |
| None | _____ |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|-------|
| <1 Ft. | _____ |
| 1 to 5 Ft. | _____ |
| Over 5 Ft. | X |

| Accessible | |
|--------------|-------|
| Within Reach | _____ |
| Barely | X |
| Unreachable | _____ |

| Texture | |
|----------|-------|
| Rough | _____ |
| Pitted | _____ |
| Moderate | X |
| Smooth | _____ |

| Adjacent Rooms | |
|----------------|-------|
| Gymnasium | _____ |
| Music Rm. | _____ |
| Mech. Rm. | _____ |
| Elevators | _____ |

AIR FLOW FACTORS

| Barriers | |
|--------------|-------|
| Permanent | _____ |
| Encapsulated | _____ |
| None | X |
| Enclosed | _____ |

| Ventilation | |
|----------------|-------|
| Yes | _____ |
| None | _____ |
| If Yes, Intake | _____ |
| Exhaust | _____ |

| Air Movement | |
|--------------|-------|
| High | _____ |
| Moderate | _____ |
| Low | _____ |

| Air Conduits | |
|--------------|-------|
| Air Plenum | _____ |
| Air Shaft | _____ |
| Elevator | _____ |
| Shaft | _____ |

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
REINSPECTION SUMMARY TABLE**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/20/2007

| Homogeneous Area (#), Type of Materials | Sampled 2004 (Y/N) | Friable 2004 (Y/N) | Changes 2007 (Y/N) | Friable 2007 (Y/N) | Sampled 2007 (Y/N) | AHERA Class. | Response Action | Hazard Rank # | Schedule (Initial - Completion) |
|--|--------------------|--------------------|--------------------|--------------------|--------------------|--------------|-----------------|---------------|---------------------------------|
| Mud Pipe Fittings | N | Y | N | Y | N | 5 | O&M | 2 | Ongoing |
| 9"x9" floor tile | N | N | N | N | Y | N/A | O&M | 1 | Ongoing |
| Window Glazing | N/A | N/A | N/A | N | N | N/A | O&M | 1 | Ongoing |
| One damaged Pipe Fitting in S-2 | | | | | | | RM | 4 | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

KEY:

| | | |
|-------------------------------|------------------------|----------------------------------|
| <u>Homogeneous Area</u> | <u>Response Action</u> | |
| T - Thermal System Insulation | RM - Remove | O&M - Operations and Maintenance |
| S - Surfacing Material | RP - Repair | ISL - Isolate |
| M - Miscellaneous | ECP - Encapsulate | |

C&R Environmental Associates, Inc.
 1415 Bush Street, 2nd Floor
 Baltimore, MD 21230

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
Resource Evaluation**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 7/20/2007

Costs are projected for removing and for repairing and encapsulating the ACMs assessed during the AHERA Building Re-inspection. The cost estimates are based upon unit cost rates for abatement of various ACMs and are provided for general planning purposes only. Many project-specific factors, including economies of scale, contract and schedule requirements, etc. will affect the actual costs for abatement. The cost estimates provided do not include the cost of replacement of the materials removed or for professional Industrial Hygiene Services, such as project design and air monitoring.

The following pages show response action costs, which are based upon an assessment of the potential health hazard as reflected by the hazard ranking. The hazard ranking system derives from the Hazard Potential Algorithm used by the AHERA Building Inspector to assess the condition of ACM and was approved for use in this reinspection by the Harford County Public Schools AHERA designated person.

Generally, the following Hazard Ranking Values initiate the following actions:

| Hazard Ranking | Response Action |
|----------------|---|
| 6 | Schedule for immediate removal. |
| 5 | Schedule for immediate action (repair/encapsulation or removal). |
| 4 | Monitor. Schedule for near term action. |
| 3 | Monitor. Schedule for future removal. |
| 2 | Monitor. As long as ACM condition does not change or use of area in which ACM exists does not change, schedule for removal later when monies are available. |
| 1 | Monitor. Generally no other action is required unless the building is renovated or demolished. |

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update**

**Budgetary Costs by Hazard Ranking
Harford County Public Schools**

| Material | Quantity | Repair/ Encapsulate | Remove |
|--|-----------|------------------------|-----------|
| A. Damaged ACM, Hazard Categories 3, 4, 5, 6 | | | |
| <u>Hazard Category 6</u> N/A | | | |
| <u>Hazard Category 5</u> N/A | | | |
| <u>Hazard Category 4</u> Mud pipe fitting in Room S-2 | 1 | | \$ 350.00 |
| <u>Hazard Category 3</u> N/A | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| B. Undamaged ACM, Hazard Categories 1, 2 | | | |
| <u>Hazard Category 2</u> | | | |
| Mud Pipe Fittings | 410 | N/A | \$10,250 |
| <u>Hazard Category 1</u> | | | |
| 9"x9" floor tile | 20,000 sf | N/A | \$70,000 |
| window glazing | 500 lf | N/A | \$15,000 |
| | | | |
| | | | |
| | | | |
| | | | |

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

CHARLES R. MCELENEY

*has met the attendance requirements and successfully completed
the course entitled*

8-Hr EPA AHERA Insp/Mgmt Planner Refresher

For Accreditation Under TSCA Title II.

10/2/2007

Course Date

10/2/2007


Exam Date

10/1/2008

Expiration Date

ROBERTA SPRATT-RITTER

Principal Instructor



92527

Certification No.

VA92527

Virginia Certification No.

E. RUSH BARNETT

Course Director



1331 Ashton Road

P.O. Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

MEMORANDUM

2209 Conowingo Road, Bel Air MD 21015 410.638.4088 FAX:410.638.4205

To: All Principals
From: Laura M. Paligo
Environmental Compliance Coordinator
Subject: Reinspections for AHERA Compliance
Date: August 23, 2004

The Asbestos Hazard Emergency Response Act (AHERA) requires all Local Education Agencies (LEAs) to complete inspections that identify asbestos containing materials (ACM) in all school buildings. Results of the inspection must then be compiled in a Management Plan to instruct building occupants, maintenance staff, parents, and any other interested parties how to safely and effectively manage any asbestos identified during the inspection.

Following the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens, and McCoy conducted the initial inspection for most of the schools in Harford County. The first reinspection was performed in 1992 by I-TEM, Ltd. The next reinspections were performed in 1995 by Testwell Craig Testing Laboratories, Inc., 1998 by Brook Environmental and Engineering Corporation, and 2001 by Jenkins Environmental Inc. This year's reinspection will be performed by C & R Environmental, Inc.

The reinspections involve visual inspection, collecting samples of some building materials for analysis, and updating management plans. Any samples taken will be small and the sample locations will be patched. The on site work will require several days at each building. Activities connected with the reinspections will require contractor personnel to work in the school building during regular school hours and some evening hours. Scheduling will require cooperation between the school, contractor, and Facilities Department personnel.

Site work will begin around August 17, 2004. You will receive the school's copy of the reinspection report as it becomes available. Each site will be notified as the details in scheduling are finalized. Please inform building occupants of the upcoming activities. Please call me at ext. 4088 if you have any questions.

pc: Patti Jo Beard

Reliability is the FOUNDATION of our Quality Service

HARFORD COUNTY PUBLIC SCHOOLS FACILITIES MANAGEMENT

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace Middle School

ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089

DATE: 9/28/2004

EPA ACCREDITED INSPECTOR/ACCREDITATION NO.: Charles McEleney MD # 75043

SIGNATURE: *Charles McEleney*

EPA MANAGEMENT PLANNER/ACCREDITATION NO.: Charles McEleney MD # 75043

SIGNATURE: *Charles McEleney*

PREVIOUSLY IDENTIFIED OR ASSUMED ACM:

Throughout

mudded pipe fittings - 421 fittings

Storage Rooms

9"x9" floor tile - 150 sf

9"x9" floor tile mastic - 150 sf

CHANGES IN MATERIAL CONDITION:

None

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

Floor tile information presented in 2002 reinspection report is not accurate. See notes on next page.

Mud fittings were removed from Mech Rm M-2 in 2002.

Small scale projects to remove window glazing have been undertaken.

NEWLY IDENTIFIED/SAMPLED MATERIALS:

Exterior

Window glazing was identified to be ACM through BOE testing since 2002.

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
BULK SAMPLE DOCUMENTATION**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 9/28/2004
COLLECTED BY: Charles R. McEleney

| Sample No. | Friable | | Homogeneous Area | Description of Exact Location | Percent Asbestos |
|-------------|---------|----|-----------------------------|-------------------------------|------------------|
| | Yes | No | | | |
| HGM-1-0928a | | X | 9"x9" Tan Floor Tile | Room 27, near door threshold | 2% Chrysotile |
| HGM-1-0928b | | x | 9"x9" Tan Floor Tile Mastic | Room 27, near door threshold | NAD |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

NAD = No Asbestos Detected

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 9/28/2004
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---|-----------------------------|
| Material Type: <u>Mud Pipe Fittings</u> | Location: <u>Throughout</u> |
| Area: <u> </u> Sq. Ft. <u> </u> Ln. Ft. <u> </u> | <u>410</u> |

COMMENTS (Optional)

Mud pipe fittings are present on fiberglass insulated piping. The material is located above the metal pan ceiling throughout the building. The fittings are intact and in good condition. Four fittings are exposed below the ceiling in M-2.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|-----------------|
| Significant | <u> </u> |
| Moderate | <u> </u> |
| Light | <u> </u> |
| None | <u>X</u> |

| Water | |
|-----------|-----------------|
| Extensive | <u> </u> |
| Moderate | <u> </u> |
| Slight | <u> </u> |
| None | <u>X</u> |

| Deterioration | |
|---------------|-----------------|
| Heavy | <u> </u> |
| Moderate | <u> </u> |
| Light | <u>X</u> |
| None | <u> </u> |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|-----------------|
| <1 Ft. | <u> </u> |
| 1 to 5 Ft. | <u> </u> |
| Over 5 Ft. | <u>X</u> |

| Accessible | |
|--------------|-----------------|
| Within Reach | <u> </u> |
| Barely | <u>X</u> |
| Unreachable | <u> </u> |

| Texture | |
|----------|-----------------|
| Rough | <u> </u> |
| Pitted | <u> </u> |
| Moderate | <u>X</u> |
| Smooth | <u> </u> |

| Adjacent Rooms | |
|----------------|-----------------|
| Gymnasium | <u> </u> |
| Music Rm. | <u> </u> |
| Mech. Rm. | <u> </u> |
| Elevators | <u> </u> |

AIR FLOW FACTORS

| Barriers | |
|--------------|-----------------|
| Permanent | <u> </u> |
| Encapsulated | <u> </u> |
| None | <u>X</u> |
| Enclosed | <u> </u> |

| Ventilation | |
|----------------|-----------------|
| Yes | <u> </u> |
| None | <u> </u> |
| If Yes, Intake | <u> </u> |
| Exhaust | <u> </u> |

| Air Movement | |
|--------------|-----------------|
| High | <u> </u> |
| Moderate | <u> </u> |
| Low | <u> </u> |

| Air Conduits | |
|--------------|-----------------|
| Air Plenum | <u> </u> |
| Air Shaft | <u> </u> |
| Elevator | <u> </u> |
| Shaft | <u> </u> |

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
Resource Evaluation**

FACILITY: Havre De Grace Middle School
ADDRESS: 7401 Lewis Lane, Havre De Grace, MD 21078-3089
DATE: 9/28/2004

Costs are projected for removing and for repairing and encapsulating the ACMs assessed during the AHERA Building Re-inspection. The cost estimates are based upon unit cost rates for abatement of various ACMs and are provided for general planning purposes only. Many project-specific factors, including economies of scale, contract and schedule requirements, etc. will affect the actual costs for abatement. The cost estimates provided do not include the cost of replacement of the materials removed or for professional Industrial Hygiene Services, such as project design and air monitoring.

The following pages show response action costs, which are based upon an assessment of the potential health hazard as reflected by the hazard ranking. The hazard ranking system derives from the Hazard Potential Algorithm used by the AHERA Building Inspector to assess the condition of ACM and was approved for use in this reinspection by the Harford County Public Schools AHERA designated person.

Generally, the following Hazard Ranking Values initiate the following actions:

| Hazard Ranking | Response Action |
|----------------|---|
| 6 | Schedule for immediate removal. |
| 5 | Schedule for immediate action (repair/encapsulation or removal). |
| 4 | Monitor. Schedule for near term action. |
| 3 | Monitor. Schedule for future removal. |
| 2 | Monitor. As long as ACM condition does not change or use of area in which ACM exists does not change, schedule for removal later when monies are available. |
| 1 | Monitor. Generally no other action is required unless the building is renovated or demolished. |

AEROSOL MONITORING & ANALYSIS, INC.

THIS IS TO CERTIFY THAT

CHARLES R. MCELENEY

HAS MET THE ATTENDANCE REQUIREMENTS AND SUCCESSFULLY COMPLETED
THE COURSE ENTITLED

8-HR EPA AHERA INSP/MGMT PLANNER RECERTIFICATION

For Accreditation Under TSCA Title II.

7/9/2004

COURSE DATE

E. RUSH BARNETT

COURSE DIRECTOR

E. Rush Barnett

7/9/2005

EXPIRATION DATE

MD-074053

CERTIFICATE NO.

7/9/2004

EXAM DATE

1331 Ashton Road

P.O. Box 646

Hanover, MD 21076

410-684-3327

FAX: 410-684-3724

MEMORANDUM

2209 Conowingo Road Bel Air MD 21015 410.638.4088 FAX:410.638.4205

To: All Principals

From: Laura M. Paligo
Environmental Compliance Coordinator

Subject: Reinspections for AHERA Compliance

Date: December 19, 2001

The Asbestos Hazard Emergency Response Act (AHERA) requires all Local Education Agencies (LEAs) to complete inspections that identify asbestos containing materials (ACM) in all school buildings. Results of the inspection must then be compiled in a Management Plan to instruct building occupants, maintenance staff, parents, and any other interested parties how to safely and effectively manage any asbestos identified during the inspection.

Following the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens, and McCoy conducted the initial inspection for most of the schools in Harford County. The first reinspection was performed in 1992 by I-TEM, Ltd. The next reinspections were performed in 1995 by Testwell Craig Testing Laboratories, Inc. and in 1998 by Brook Environmental and Engineering Corporation. This year's reinspection will be conducted by Jenkins Environmental Inc.

The reinspections involve visual inspection, collecting samples of some building materials for analysis, and updating management plans. Any samples taken will be small and the sample locations will be patched. The on site work will require several days at each building. Activities connected with the reinspections will require contractor personnel to work in the school building during regular school hours and some evening hours. Scheduling will require cooperation between the school, contractor, and Facilities Department personnel.

Site work will begin around December 19, 2001 and will continue through early next year. You will receive the school's copy of the reinspection report as it becomes available. Each site will be notified as the details in scheduling are finalized. Please inform building occupants of the upcoming activities. Please call me at ext. 4088 if you have any questions.

pc: Patti Jo Beard
Jeffrey C. Ayers

AHERA Three (3) Year Re-inspection Form
AHERA Management Plan Update

Havre De Grace M.S.
(Facility)

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

TABLE 1.02
CHANGES IN MATERIAL CONDITION

| Ref. No. | Material Description | Location | Quantity | Comments |
|----------|----------------------|----------------------|----------|----------------|
| 12 | mudded pipe fitting | can room off kitchen | 4 | abated 11/2000 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

- Ref. 12 - abated (4) mudded pipe fittings

AHERA Three (3) Year Re-inspection Form
AHERA Management Plan Update

Havre De Grace M.S.
(Facility)

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

SECTION 2.0 CURRENT CONDITIONS REPORT

TABLE 2.01
NEWLY IDENTIFIED/SAMPLED ACM MATERIALS
(Only samples testing positive for asbestos content are reported in Table 2.01)

| Ref. No. | Sample No. ¹ | Material Description | Location | Quantity |
|----------|-------------------------|--------------------------|-------------------------|----------|
| 8 | HDGHS 1 | 9" tan floor tile | storage room by room 28 | 150 SF |
| 9 | HDGHS 2 | 9" tan floor tile mastic | storage room by room 34 | 150 SF |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

1. Chain-of-Custody forms and Certificates of Analysis are attached.

ADDITIONAL COMMENTS:

- bulk samples were taken of 9" tan floor tile, nothing in management plan but positive for floor tile and floor tile mastic

*Insufficient sampling of 9x9" and mastic.
assume all 9x9 is pos. & mastic is positive?*

**AHERA Three (3) Year Re-inspection Form
AHERA Management Plan Update**

Havre De Grace M.S.
(Facility)

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

**TABLE 2.02
ACM MATERIALS REMAINING IN BUILDING**

| Ref. No. | Material Description | Location | Quantity | ACM Condition |
|----------|----------------------|---------------|----------|---------------|
| 12 | mudded pipe fittings | throughout | 421 | good |
| 8 | 9" tan floor tile | storage rooms | 150 SF | good |
| 9 | 9" floor tile mastic | storage rooms | 150 SF | good |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

RECOMMENDED ACTION(S):

Table 3.0 ABATEMENT COST ESTIMATE REPORT

| REF # | HOMOGENEOUS MATERIAL DESCRIPTIONS | Class. (1) | Quantity | Cost Estimates |
|--|-----------------------------------|------------|----------|----------------|
| 1 | Boiler Insulation (SF) | T | 0.00 | \$0.00 |
| 2 | Breeching Insulation (SF) | T | 0.00 | \$0.00 |
| 3 | Tank Insulation (SF) | T | 0.00 | \$0.00 |
| 4 | Duct Insulation (SF) | T | 0.00 | \$0.00 |
| 5 | Pipe Insulation (LF) | T | 0.00 | \$0.00 |
| 6 | Converter (SF) | T | 0.00 | \$0.00 |
| 7 | Sprayed On Insulation (SF) | S | 0.00 | \$0.00 |
| 8 | 9" Floor Tile (SF) | M | 150.00 | \$525.00 |
| 9 | 9" Floor Tile Mastic (SF) | M | 150.00 | \$225.00 |
| 10 | 12" Floor Tile (SF) | M | 0.00 | \$0.00 |
| 11 | 12" Floor Tile Mastic (SF) | M | 0.00 | \$0.00 |
| 12 | Mudded Pipe Fittings (ea) | T | 421.00 | \$10,525.00 |
| 13 | Fire Doors (ea) | M | 0.00 | \$0.00* |
| 14 | Exterior Transite (SF) | M | 0.00 | \$0.00 |
| 15 | Suspect Asbestos Debris (SF) | T | 0.00 | \$0.00 |
| 16 | Vibration Collars (LF) | T | 0.00 | \$0.00 |
| 17 | 2 X 4 Drop Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 18 | 2 X 2 Drop Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 19 | Spline Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 20 | 1' X 1' Glued Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 21 | Glue spots (SF) | M | 0.00 | \$0.00 |
| 22 | Unit Ventilator Insulation (SF) | T | 0.00 | \$0.00 |
| 23 | Roof Drain Fittings (ea) | M | 0.00 | \$0.00 |
| 24 | Stagelight Wiring (LF) | M | 0.00 | \$0.00* |
| 25 | Resilient Sheetgood Material (SF) | M | 0.00 | \$0.00 |
| 26 | Gasket Material (LF) | M | 0.00 | \$0.00* |
| 27 | Asbestos Plaster (SF) | M | 0.00 | \$0.00 |
| 28 | | | 0.00 | \$0.00 |
| 29 | | | 0.00 | \$0.00 |
| 30 | | | 0.00 | \$0.00 |
| 31 | | | 0.00 | \$0.00 |
| 32 | | | 0.00 | \$0.00 |
| 33 | | | 0.00 | \$0.00 |
| 34 | | | 0.00 | \$0.00 |
| 35 | | | 0.00 | \$0.00 |
| 36 | | | 0.00 | \$0.00 |
| 37 | | | 0.00 | \$0.00 |
| 38 | | | 0.00 | \$0.00 |
| 39 | | | 0.00 | \$0.00 |
| Total Cost of Full ACM Removal From School | | | 0.00 | \$11,275.00 |
| bestos Classification | | | | |
| M | Miscellaneous Materials | | | |
| T | Thermal System Insulation (TSI) | | | |
| S | Surfacing Material | | | |

* 1.0 = quantity unknown, default value = \$1000

School: Havre De Grace Middle School
Address: 7401 Lewis Lane
Havre De Grace, MD 21078-3089
Date of Inspection: August 14, 1998

SECTIONS

SECTION 1.0 ACCREDITATION INFORMATION

SECTION 2.0 HARFORD SUMMARY FORM

SECTION 3.0 BROOK ADDENDUM SUMMARY FORM

**SECTION 4.0 HOMOGENOUS AREA ASSESSMENT TABLE AND
FRIABLE HOMOGENOUS AREA ASSESSMENT LOG**

SECTION 5.0 LABORATORY RESULTS

SECTION 6.0 CERTIFICATIONS

SECTION 7.0 ATTACHMENTS

- A. Response Action Determination**
- B. Operations and Maintenance Program**
- C. AHERA Classifications**
- D. Decision Tree**
- E. Glossary**

SECTION 1.0

Brook Environmental & Engineering Corporation Accreditation

Brook Environmental & Engineering Corporation (Brook) accredited personnel performed this re-inspection, collected bulk samples (if necessary), provided the assessments and response action recommendations for Harford County Public Schools

Inspections, Bulk Sampling, and Assessments

- Re-inspections were conducted by: Beth L. Schmuter
- Bulk Samples were collected by: N/A
- Assessments were made by: Beth L. Schmuter

Management Planner

- Recommendations for Response Actions made by: Brian J. Hug

Personnel

Name: Beth L. Schmuter Signature: Beth Schmuter
Title: Asbestos Inspector
Accreditation Number/ State: 035521/ Maryland
Date of Expiration: August 10, 1999

Name: Brian J. Hug Signature: Brian J. Hug
Title: Management Planner
Accreditation Number/ State: 035323/ Maryland
Date of Expiration: June 5, 1999

2.0 HARFORD COUNTY SUMMARY FORM

**AHERA Three (3) Year Re-inspection Form
AHERA Management Plan Update**

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

1. **Facility:** Havre de Grace Middle School
2. **Address:** 7401 Lewis Lane, Havre De Grace MD 21078-3089
3. **Date:** 8/7/98
4. **EPA Accredited Inspector(s):** Beth L. Schmuter
5. **Signature(s):** Beth Schmuter
6. **Previously Identified and/ or assumed ACM (all materials are assigned "material numbers"):**
 - (1) Throughout Building- Pipe Fittings on F/G Insulation, approx. 425 each
 - (2) Auditorium- Stage Light Wire Insulation

7. Changes in Material Condition (by material number): None

1) A previous asbestos survey reported one (1) fitting in the mechanical room in poor condition. Brook Environmental and Engineering Corp. observed all fittings in the mechanical room to be in good condition.

8. Additional Comments/ Abatement Projects:

Several fittings in the mechanical room were replaced with fiberglass. There are a total of seven (7) fittings remaining in the mechanical room which are asbestos containing, in addition to the fittings throughout the school.

8. Newly Identified/ Sampled Materials (All new materials are assigned the next highest available number):

None

10. Remaining ACM in Building (Section 6 minus Section 8, plus section 9 materials):

a. Previously Identified Materials

(1) Throughout Building- Pipe Fittings on F/G Insulation, approx. 425 each

(2) Auditorium- Stage Light Wire Insulation

b. Newly Identified Materials

None

3.0 BROOK ADDENDUM SUMMARY FORM

AHERA Classification Section

- | | |
|-------------------------------------|---|
| (1) Pipe Fittings on F/G Insulation | 5 ACBM with potential for damage. |
| (2) Stage Light Wire Insulation | 8 Non-Friable Surfacing or Miscellaneous ACM. |

Homogenous Area Assessment

- (1) Pipe Fittings on F/G Insulation:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

- (2) Stage Light Wire Insulation:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

Harford County 3 Year Re-inspection, Havre De Grace Middle Sch. September 17, 1998
Brook Project: 98-7-443

This facility, Havre De Grace Middle School contains ACM.

The Facility shall be re-inspected by an AHERA accredited inspector by August of 2001, and every three years thereafter until all materials, known or assumed to be ACM, have been removed.

Harford County 3 Year Re-inspection, Havre De Grace Middle Sch. September 17, 1998
Brook Project: 98-7-443

4.0 HOMOGENOUS AREA ASSESSMENT TABLE

AND

FRIABLE HOMOGENOUS AREA ASSESSMENT LOG

Homogenous Area Assessment Table

School: HAIRE DE GRACE MIDDLE SCHOOL

| Homogenous Area (#), Type of Material | Sampled 1994-95 (Y/N) | Friable 1994-95 (Y/N) | Changes 1998 (Y/N) | Friable 1998 (Y/N) | Sampled 1998 (Y/N) | AHERA Class. | Response Action | Res. Act. # | Schedule (Initial - Completion) |
|---|-----------------------|-----------------------|--|--------------------|--------------------|--------------|-----------------|-------------|---------------------------------|
| ① THROUGHOUT BLDG. - FITTINGS ON F.G. PIPES (T) | N | Y | SOME FITTINGS IN BOILER ROOM WERE REPLACED. SEVEN (?) ACM FITTINGS REMAIN IN BOILER ROOM | Y | N | 5 | O+M | 8 | 8/7/98 to REMOVAL |
| | | | AND ANOTHER APPROX 420 THROUGHOUT BLDG. ALL FITTINGS OBSERVED IN GOOD CONDITION. | | | | | | |
| ② Auditorium - STAGE LIGHT WIRE INSULATION (T) | N | N | N | N | N | 8 | O+M | 8 | 8/7/98 to REMOVAL |

Key:

Classifications: Please See Attachment

Homogenous Area

T - Thermal System Insulation
 S - Surfacing Material
 M - Miscellaneous

Response Action

RM - Remove
 RP - Repair
 ECP - Encapsulate
 O&M - Operations and Management
 ISL - Isolate

Homogenous Area Assessment Table

School: MAIRE DE GRACE - MIDDLE

| Homogenous Area (#), Type of Material | Sampled 1994-95 (Y/N) | Friable 1994-95 (Y/N) | Changes 1998 (Y/N) | Friable 1998 (Y/N) | Sampled 1998 (Y/N) | AHERA Class. | Response Action | Res. Act. # | Schedule (Initial - Completion) |
|--|-----------------------|-----------------------|--------------------|--------------------|--------------------|--------------|-----------------|-------------|---------------------------------|
| ③ AIR HANDLERS - HVAC ISOLATOR VIBRATION CLOTHS (M) | N | N | N | N | N | 5 | O&M | 8 | 8/7/98 to REMOVAL |
| | | | | | | | | | |
| | | | | | | | | | |

Key:

Classifications: Please See Attachment

Homogenous Area

- T - Thermal System Insulation
- S - Surfacing Material
- M - Miscellaneous

Response Action

- RM - Remove
- RP - Repair
- ECP - Encapsulate
- O&M - Operations and Management
- ISL - Isolate

FRIABLE HOMOGENEOUS AREA-ASSESSMENT

Page _____

Name of School HAVRE DE GRACE MIDDLE

Date Aug. 7, 1998

Inspector B. SCHMUTER

Sample ID _____

| | |
|---|-----------------------------------|
| Material Type: <u>FITTINGS</u> | Location: <u>THROUGHOUT BLDG.</u> |
| Area: _____ Sq.Ft. _____ Ln.Ft. <u>420 EACH</u> | |

COMMENTS (OPTIONAL)

SEVERAL FITTINGS WERE REPLACED IN THE BOILER ROOM. THE FITTING PREVIOUSLY REPORTED IN POOR CONDITION HAS BEEN REMOVED. SEVEN (7) ACM FITTINGS REMAIN IN THE BOILER ROOM.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| |
|-------------------|
| Physical |
| Significant _____ |
| Moderate _____ |
| None <u>X</u> |

| |
|-----------------|
| Water |
| Extensive _____ |
| Moderate _____ |
| Slight _____ |
| None <u>X</u> |

| |
|----------------------|
| Deterioration |
| Heavy _____ |
| Moderate _____ |
| Light _____ |
| None <u>X</u> |

DISTURBANCE FACTORS

| |
|----------------------------------|
| Proximity to Repair items |
| < 1ft. _____ |
| 1 to 5ft. <u>N/A</u> |
| Over 5ft. _____ |

| |
|-----------------------|
| Accessible |
| Within reach <u>X</u> |
| Barely _____ |
| Unreachable _____ |

| |
|-------------------|
| Texture |
| Rough _____ |
| Pitted _____ |
| Moderate <u>X</u> |
| Smooth _____ |

| |
|-----------------------|
| Adjacent Rooms |
| Gymnasium <u>X</u> |
| Music Rm. <u>X</u> |
| Mech. Rm. <u>X</u> |
| Elevators <u>X</u> |

AIR FLOW FACTORS

| |
|--------------------|
| Barriers |
| Permanent _____ |
| Enclosed _____ |
| Encapsulated _____ |
| None <u>X</u> |

| |
|----------------------|
| Ventilation |
| Yes <u>X</u> |
| No _____ |
| If yes, intake _____ |
| exhaust _____ |

| |
|---------------------|
| Air Movement |
| High _____ |
| Moderate _____ |
| Low <u>X</u> |


| |
|---------------------|
| Air Conduits |
| Air plenum <u>X</u> |
| Air shaft _____ |
| Elevator _____ |
| Shaft _____ |

5.0 LABORATORY RESULTS

There were no bulk samples taken at the subject facility.

Harford County 3 Year Re-inspection, Havre De Grace Middle Sch. September 17, 1998
Brook Project: 98-7-443

6.0 CERTIFICATIONS



ManTech Environmental Corporation
1901 Research Blvd, Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

BRIAN J. HUG

has successfully completed an EPA approved course and examination for

AHERA Management Planner—16 Hours

and has completed training for accreditation under TSCA Title II

June 4-5, 1998

Location of Training: Rockville, MD

Certificate Number: 98-06-05-02

Certificate Expires: June 5, 1999

Exam Date: June 5, 1998

Alex Baylor

Instructor: Alex Baylor

Rachel Riley

Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation



Printed on recycled paper



ManTech Environmental Corporation
1901 Research Blvd, Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

KAREN KARKUT

has successfully completed an EPA approved course and examination for

AHERA Building Inspector—24 Hours

and has completed training for accreditation under TSCA Title II



June 1-3, 1998

Location of Training: Rockville, MD

Certificate Number: 98-06-03-03

Certificate Expires: June 3, 1999


Exam Date: June 3, 1998


Instructor: Daniel Bennett, CET

Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation





ManTech Environmental Corporation
1901 Research Blvd, Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

BRIAN J. HUG

has successfully completed an EPA approved course and examination for

AHERA Building Inspector Refresher—4 Hours

and has completed training for accreditation under TSCA Title II

May 27, 1998

Location of Training: Rockville, MD

Certificate Number: 98-05-27-01

Certificate Expires: May 27, 1999

Exam Date: May 27, 1998



Instructor: Daniel Bennett, CET


Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation





ManTech Environmental Corporation
1901 Research Blvd., Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

BETH SCHMUTER

has successfully completed an EPA approved course and examination for

AHERA Building Inspector Refresher—4 Hours

and has completed training for accreditation under TSCA Title II

August 10, 1998


Location of Training: Rockville, MD

Certificate Number: 98-08-10-09

Certificate Expires: August 10, 1999

Exam Date: August 10, 1998


Instructor: Rachel Riley, CET


Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation



7.0 ATTACHMENTS

***(NOTE TO READER: SECTION 7.0 WAS
DELIVERED TO THE CLIENT UNDER A SEPARATE
COVER.)***

Harford County 3 Year Re-inspection, Havre De Grace Middle Sch. September 17, 1998
Brook Project: 98-7-443

Limitations and Exclusions

All the professional opinions presented in this report are based solely on the scope of work conducted and sources referred to in our report. The data presented by Brook in this report was collected and analyzed using generally accepted industry methods and practices at the time the report was generated. This report represents the conditions, locations, and materials that were observed at the time the field work was conducted. No inferences regarding other conditions, locations, or materials, at a later or earlier time may be made based on the contents of the report. Brook's liability and that of its contractors and subcontractors, arising from any services rendered hereunder, shall not exceed the total fee paid by the client to Brook for this project. No other warranty, express or implied is made. The accuracy of this report is limited to the accuracy of the information obtained by Brook. This report was prepared for the sole use of our client. The use of this report by anyone other than our client or Brook is strictly prohibited without the expressed prior written consent of Brook. Portions of this report may not be used independent of the entire report.

MEMORANDUM

TO: All Principals
FROM: Patti Jo Beard
SUBJECT: Reinspections for AHERA Compliance
DATE: July 28, 1995

The Asbestos Hazard Emergency Response Act (AHERA) requires all Local Education Agencies (LEA's) to complete inspections that identify asbestos containing materials (ACM) in all school buildings. Results of the inspection must then be compiled in a management plan to instruct building occupants, maintenance staff, parents, and any interest parties how to safely and effectively manage any asbestos identified during the inspection.

Following the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens, and McCoy conducted the initial inspection for Harford County Public Schools. In 1992, the first reinspection was completed by i-TEM, Ltd. This year's reinspection will be conducted by Testwell Craig Testing Laboratories, Inc.

The reinspections will involve visual inspection, taking samples of some building materials for analysis and updating current management plans. Any samples taken will be very small and the sample locations will be patched. The actual site work will require a few days at each building. Activities connected with the inspections will require contractor personnel to work in the school during the regular working day and some evening hours. Scheduling will require cooperation between school, contractor and Facilities Department personnel.

Site work will begin the first week of August and continue through the month. All documentation will be done by the first week of October. As the updated documents become available, you will receive the school's copy. Each site will be notified as the details in scheduling are finalized. Please inform building occupants of the upcoming activities. If there any questions, please do not hesitate to contact me.

slb


pc: Roger C. Niles
Jeffrey C. Ayers

LETTER OF ASSURANCE
THREE-YEAR REINSPECTION OF SCHOOL BUILDINGS PURSUANT TO AHERA

RESPONSIBLE GOVERNING AUTHORITY

| | | |
|---|--|---|
| Name of Responsible Governing Authority HARFORD COUNTY PUBLIC SCHOOLS | | Telephone Number (410) 838-7300 |
| Street Address 2209 CONOWINGO ROAD | | |
| Town BEL AIR, MARYLAND 21015 | | County HARFORD |
| Name of Asbestos Program Manager PATTI JO BEARD | Affiliation 2209 CONOWINGO ROAD, BEL AIR, MARYLAND 21015 | Telephone Number (410) 638-4204 |
| Name of Facility HAVRE DE GRACE MIDDLE SCHOOL | | Telephone Number (410) 939-6608 |
| Building Assessed HAVRE DE GRACE MIDDLE SCHOOL | Asb. Mgt. Plan Number | |
| Street Address 401 LEWIS LANE | | |
| Town HAVRE DE GRACE, MARYLAND 21078-3799 | | County HARFORD |
| Date Three-Year Reinspection Occurred AUG 07, 1995 | | |

INSPECTORS/ASSESSORS

| | | | |
|---|---|---|--|
| 1 | Name: WILLIAM THAW | Address: 5429 E. HARDING HIGHWAY MAYS LANDING, NJ 08330 | Telephone Number (609) 625-1700 |
| | Affiliation: TESTWELL CRAIG TESTING LABS., INC. | State of Accreditation/Acc. No. MD 12979 | Signature  |
| 2 | Name: | Address | Telephone Number |
| | Affiliation | State of Accreditation/Acc. No. | Signature |
| 3 | Name | Address | Telephone Number |
| | Affiliation | State of Accreditation/Acc. No. | Signature |

GENERAL INFORMATION

Name of Facility: HAVRE DE GRACE MIDDLE SCHOOL

Building Assessed: HAVRE DE GRACE MIDDLE SCHOOL

Building Description:

HAVRE DE GRACE MIDDLE SCHOOL IS A 1 STORY BUILDING CONSTRUCTED IN 1955.
ADDITIONS WERE MADE IN 1958, 1971, 1976 AND 1984. NO RENOVATIONS WERE
MADE.

Inspection Description:

THE HAVRE DE GRACE MIDDLE SCHOOL WAS INSPECTED ON AUGUST 7, 1995 BY
WILLIAM THAW OF TESTWELL CRAIG TESTING LABORATORIES, INC.

PREVIOUSLY DETERMINED ACBM IN BUILDINGS:

FITTING ON F/G LINES 425.

ADDITIONS: STAGE LIGHT WIRING INSULATION, VIBRATION COLLARS ON AIR
HANDLERS 16 EACH.

HAVRE DE GRACE MIDDLE SCHOOL

NO DAMAGE TO REPORT

ALL OTHER PREVIOUSLY
DETERMINED & ADDITIONAL ACBM


WAS FOUND TO BE IN GOOD CONDITION AT TIME
OF INSPECTION

WILLIAM THAW

TECHNICIAN NAME:

W. E. Thaw

TECHNICIAN SIGNATURE



CERTIFICATE NUMBER: 12979

THIS IS TO CERTIFY THAT

William E. Thaw

**HAS MET THE ATTENDANCE REQUIREMENTS
AND SUCCESSFULLY COMPLETED THE EXAM
IN THE COURSE ENTITLED**

ASBESTOS BUILDING INSPECTOR

EPA APPROVED COURSE UNDER TITLE II RULE

Environmental Training, Inc.

TRAINING PROVIDER

January 30 - February 1, 1995

COURSE DATE

1702 Industrial Highway, Suite 7

ADDRESS

February 1, 1996

EXPIRATION DATE

31-00-01-BI

COURSE APPROVAL NUMBER

William E. Thaw
STUDENT'S SIGNATURE

William Harcourt

COURSE DIRECTOR (NAME AND SIGNATURE)

STATE OF MARYLAND

REG # 007612



AHERA/EPA Accredited
Per 40 CFR Part 763


Certificate of Completion

This is to certify that John J. Gordon S/S #173-28-0758

has successfully completed the course entitled EPA/AHERA/N.Y. State 1/2 Day
Management Planner Refresher

on December 2, 19 94

Examination passed on N/A 19

Expiration date: Dec. 2, 1995  Dec. 2, 1994
Doris L. Adler
President Date

3321 Doris Avenue, Building B, Ocean, NJ 07712 (908) 531-5571

TO: All Principals
FROM: Patti Jo Waddell
SUBJECT: Reinspection for AHERA Compliance
DATE: March 27, 1992

The Asbestos Hazard Emergency Response Act (AHERA) requires that all Local Education Agencies (LEAs) complete inspections to identify asbestos containing materials (ACM) in all school buildings and prepare management plans to safely and effectively manage any asbestos identified during the inspection. After the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens and McCoy conducted the initial inspection for Harford County Public Schools. All reinspections for HCPS will be done by i-TEM Limited, an environmental firm.

The reinspections will involve visual inspection, taking samples of some building materials for analysis and updating current management plans. Any samples taken will be very small and the sample locations will be patched. The actual site work will only be a couple days at each school. Activities connected with the inspections may require contractor personnel to work in the school during class hours. However, every effort will be made to schedule work outside normal class hours. Scheduling will require cooperation between school, contractor and Facilities department personnel.

The reinspections will begin the first week of April and continue through June. All documentation will be done by the first week of July. As the updated documents become available, you will receive the school's copy. You will be notified as the details in scheduling are finalized. Please inform staff, students and parents of upcoming activities. An example would be "According to AHERA requirements, all schools were inspected for asbestos in 1989 and a management plan was developed. Reinspections are required once every three years. This will be done during the spring of 1992 in all Harford County Public Schools. This information is provided in compliance with AHERA regulations." If there are any questions, please do not hesitate to contact me.

bm

pc: Roger C. Niles
Joseph M. Devilbiss

**AHERA Three (3) Year Reinspection Form
AHERA Management Plan Update**


This form is to be included in the Record Keeping section of the LEA- designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

FACILITY: Havre de Grace Middle School

ADDRESS: 401 Lewis Lane Havre de Grace, MD 21078-3089

DATE: 5/6/92

EPA ACCRED. INSPECTOR: Lonnie Watson
(print)

SIGNATURE: 
(sign)

PREVIOUSLY IDENTIFIED AND/OR ASSUMED ACM:

Throughout Building
Fittings on F/G lines - 425 EA

CHANGES IN MATERIAL CONDITION:

None - One (1) damaged fitting remains in Boiler Room

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

None

NEWLY IDENTIFIED/SAMPLED MATERIALS:

None

**AHERA Three (3) Year Reinspection Form
AHERA Management Plan Update**

FACILITY: Havre de Grace Middle School

ADDRESS: 401 Lewis Lane Havre de Grace, MD 21078-3089

DATE: 5/6/92

REMAINING ACM IN BUILDING:

Throughout Building

Fittings on F/G lines - 425 EA

Fire doors



**August 2016 - AHERA 3-Year
Re-Inspection Report**

Havre De Grace High School
700 Congress Avenue
Havre De Grace, MD 21078

Prepared for:

Harford County Public Schools
102 South Hickory Avenue
Bel Air, MD, 21014

Prepared by:

SSM Group, Inc.
1047 North Park Road
Reading, PA, 19610
SSM Project No. 100368.0001

Management Plan updated by:


William M. Kathnowsky
State of Maryland
Inspector/Management Planner
(#130311)

**HARFORD COUNTY PUBLIC SCHOOLS
HAVRE DE GRACE HIGH SCHOOL
AHERA 3-YEAR RE-INSPECTION REPORT
AUGUST, 2016**

EXECUTIVE SUMMARY

The AHERA 3-Year Re-inspection of the Havre De Grace High School was conducted by Mr. William M. Katinowsky on August 2, 2016. Mr. Katinowsky is an EPA AHERA accredited Building Inspector/Management Planner, who is also licensed in the same capacity by the Maryland Department of the Environment (MDE). The re-inspection was performed in accordance with EPA 40 CFR, Part 763, which is commonly referred to as AHERA.

During the re-inspection, Mr. Katinowsky identified and assessed the condition and quantity of all known ACM, as noted in the previous re-inspection. Locations, quantities and assessment conditions are noted on the Room-by-Room Inventory of ACM included with this report. There were no damaged or significantly damaged materials found during this inspection.

ADDITIONAL MATERIAL(S) ADDED

Transite table tops were assumed during this re-inspection.

MATERIALS ADDED DURING THE 2013 INSPECTION

During the 2013 AHERA 3-year re-inspection cove base and cove base adhesive was added. Most of these materials were replacement materials of original materials and were non-asbestos containing materials. SSM recommends that since these materials were added as assumed to contain asbestos, they continue to be monitored and sampled prior to removal or renovation of the materials. SSM recommends bulk sampling only if these materials will be removed/impacted during future renovations.

BULK SAMPLING

No bulk samples were collected during this re-inspection.

RESPONSE ACTIONS

No known response actions were taken since the previous re-inspection.

CONCLUSION

1'x1' and 9"x9" floor tile and associated mastic, fitting insulation, fire doors, thermal pipe insulation, vibration collars and stage light wire insulation remain in the building. SSM discovered exposed ends on the thermal pipe insulation in the area outside the Cafeteria near the bathrooms. SSM discovered various areas in which the floor tile has slight damage. Also noted was damaged fire doors located in Cafeteria. SSM recommends that you monitor the condition of the materials and repair/ remove as necessary. Continue to handle all ACM and assumed ACM in accordance with your current Operations and Maintenance (O&M) Plan. We also remind you to continue to provide maintenance and custodial staff with annual asbestos awareness training, continue to provide annual notification to building staff, parents and guardians, and to assure that copies of all inspection reports and AHERA documentation are maintained in your central AHERA files (located in the Maintenance Facility) and at each individual school (main office in a location that is easily accessible by office staff).

Section 4-1: Material Summary and Estimated Cost of Removal for the Havre De Grace High School

| <u>Material & Location</u> | <u>Type</u> | <u>Quantity</u> | <u>Estimated Cost of Removal</u> |
|--|-------------|-----------------|----------------------------------|
| Throughout the Building | | | |
| 1'x1' Floor Tile and Mastic | M | 30,000 S.F. | \$120,000 |
| 9"x9" Floor Tile and Mastic | M | 600 S.F. | \$2,400 |
| Fitting Insulation | T | 750 Ea. | \$19,000 |
| Fire Doors | M | 20 Ea. | \$200 |
| Gym | | | |
| Vibration Collars | M | 80 S.F. | \$200 |
| Stage | | | |
| Light Wire Insulation | M | 220 L.F. | \$500 |
| Rooms 156, 159, 160, 162, 167, 227 and 403 | | | |
| Thermal Pipe Insulation | T | 540 L.F. | \$13,500 |
| 228, 230, 232 and 234 | | | |
| Transite Table Tops* | M | 320 S.F. | \$2,000 |

*= Assumed to be ACM

T= Thermal ACM

M- Miscellaneous ACM

L.F.= Linear Feet

S.F.= Square Feet

Section 6-1: Recommended Minimum Response Actions for the Havre De Grace High School

| <u>Material & Location</u> | <u>Quantity</u> | <u>Response Action</u> |
|--|-----------------|------------------------------|
| Throughout the Building | | |
| 1'x1' Floor Tile and Mastic | 30,000 S.F. | Handle Under the O&M Program |
| 9"x9" Floor Tile and Mastic | 600 S.F. | Handle Under the O&M Program |
| Fitting Insulation | 750 Ea. | Handle Under the O&M Program |
| Fire Doors | 20 Ea. | Handle Under the O&M Program |
| Gym | | |
| Vibration Collars | 80 S.F. | Handle Under the O&M Program |
| Stage | | |
| Light Wire Insulation | 220 L.F. | Handle Under the O&M Program |
| Rooms 156, 159, 160, 162, 167, 227 and 403 | | |
| Thermal Pipe Insulation | 540 L.F. | Handle Under the O&M Program |
| 228, 230, 232 and 234 | | |
| Transite Table Tops* | 320 S.F. | Handle Under the O&M Program |

*= Assumed to be ACM

L.F.= Linear Feet

S.F.= Square Feet

Algorithm Values

ALGORITHM VALUES - SHORT FORM

- Damaged Condition (DC) -
- 0 Intact, Encapsulated
 - 1 Intact, Minor Water Stain
 - 2 Intact, Cover Poor, Moderate Stain, No Damage
 - 3 Minor Damage, Scrapes, etc., Duct Tape Repair
 - 5 Damage, Fix with Patch, Repair and Encapsulate
 - 7 Significant Damage, Some Removal Needed
 - 10 Very Significant Damage, Removal Mandated
- Exposure Factor (E) -
- 0 Inaccessible or Non-friable
 - 1 Very Limited Access
 - 2 Maintenance Area Like Boiler Room or Above 2x4's
 - 3 Public Area, 10 Feet and Higher
 - 4 Public Area, 10 Feet and Lower
- Activity Level (AT) -
- 0 Behind Walls, Locked Closet, etc.
 - 1 Low or Medium Usage (1-3 Persons, 8 Hr/Day)
 - 2 #1 with Vibration or Public Area
 - 4 High Activity (Gym, Loading Dock) and/or High Vibration
- Air Flow Factor (AF) -
- 0 No Impingement, Little or No Air Flow
 - 1 Low Air Flow or Air Velocity, No Impingement
 - 2 Air Stains, Moderate Velocity, Piston Effect
 - 4 High Air Velocity, Air Erosion
- Potential Damage (PD) -
- 0 No ACM
 - 1 ACM, No Potential Damage
 - 2 Possible Potential Damage
 - 3 Potential Damage Expected
 - 4 Possible Significant Potential Damage
 - 5 Significant Potential Damage Expected
- Friability (F) -
- 1 Non-Friable, Behind Walls, etc.
 - 2 Encapsulated, Ceiling Tile, Hard Surface
 - 3 Friable - Standard ACM and Fittings
 - 5 Highly Friable - Delaminating, "Fluffy" Fireproofing
- Percent Asbestos (PA) -
- 0 = No ACM
 - 1 = >1% but <25% - Chrysotile Only
 - 2 = 25% to 80% - Chrysotile Only
 - 3 = >80% - or any percentage of amosite, crocidolite, anthophyllite, tremolite or actinolite
- Linear Feet (L) - Refers to quantity of ACM
- Square Feet (S)
- L Linear Feet
 - S Square Feet

Accreditations

Asbestos License

MDE

William Katinowski
Name

[Signature]
Signature

Inspector/Management Planner Review
Course Title

15024901



Course Date: 12/03/2015
Exp Date: 12/03/2016
Exam Date: 01/07/2016

STATE OF MARYLAND

Allsafe Environmental
Training Provider

375 Kriswell Dr
Address

Boiling Springs, PA 17007
City, State, Zip

717-258-4109
Phone

MDE

Lorraine Anderson
Name of Training Director
For additional information, call MDE (410) 537-3200

[Signature]

Form A: AHERA Three (3) Year (2013) Reinspection Data Summary

| | | | |
|--------------------------------------|------------------------------------|---|--|
| Harford County Public Schools | | | |
| 1 | LEA Point of Contact: | Cynthia Yost, Environmental Compliance Coordinator | |
| | Facility Number and Name: | | |
| 2 | Facility Address: | Havre De Grace High School | |
| | | 700 Congress Avenue, Havre De Grace, MD 21078-3089 | |
| 3 | Date of Inspection | 8/14/2010 | |
| 4 | EPA Accredited Inspector(s) | Edward Clarke MD # 120333 | |
| | | | |
| | Management Planner(s) | Joseph Williamson MD # 121323 | |
| 5 | 5A | Information provided by HCPS to Meemscop for Review: | |
| | | | |
| | | | Abatement records provided by HCPS are attached |
| | 5B | Comments and Issues: | The vibration collar in the Gym is still present and black tar paper found in the room. |
| | | | All ACM in Room 540, 528 were removed including all fire doors that were identified throughout. Covebase and covebase adhesive glue were found throughout the building. |

Form A: Homogeneous Area Assessment and Response Action Form

| 6 Previously Tested Materials with <u>no asbestos detected (NAD)</u> | | | | | | |
|--|-------------|-------------|----------------------|--------------------------|--|--|
| Homogeneous Material Description | | Location(s) | Sampling Information | | | |
| | | | Samples Adequate? | Samples Collected for HA | | |
| HA ID: M001 | Type: Misc. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M002 | Type: Misc. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M004 | Type Misc. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| | |
|---|---|
| 7 | Description of Asbestos Removal Projects during the last three years, including dates and location of work. |
| X | |
| | <p>April 15, 2011, asbestos containing glue and mastic were removed from the Media Center and Library. Full containment was utilized.</p> |
| | <p>From June 17, through July 29, 2011 asbestos containing mudded fittings, floor tile, gaskets, caulks and stage light wiring from the hallways Gym and the stage. Full containment and glovebag techniques were utilized.</p> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Form A: Homogeneous Area Assessment and Response Action Form

| 8 New suspect ACM identified during 2013 Re-inspection | | | | | |
|--|-------------|-------------|----------------------|--------------------------|--|
| Homogeneous Material Description | | Location(s) | Sampling Information | | |
| | | | ACM? | Samples Collected for HA | |
| HA ID: M007 | Type: Misc. | Throughout | A | | |
| Detail: 2 x 4 White ceiling tiles | | | | | |
| | | | | | |
| | | | | | |
| HA ID: M008 | Type: Misc. | Throughout | A | | |
| Detail: 12 x 12 Floor Tiles (Various Colors) | | | | | |
| | | | | | |
| | | | | | |
| HA ID: M010 | Type: Misc. | Throughout | A | | |
| Detail: Mastic under flooring material | | | | | |
| | | | | | |
| | | | | | |
| HA ID: M011 | Type: Misc. | Throughout | A | | |
| Detail: Ceramic Tile & Ceramic tile grout | | | | | |
| | | | | | |
| | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| 8 New suspect ACBM identified during 2013 Reinspection | | | | | | |
|--|--------------------|-------------|----------------------|--------------------------|--|--|
| Homogeneous Material Description | | Location(s) | Sampling Information | | | |
| | | | ACM? | Samples Collected for HA | | |
| HA ID: M012 | Type: Misc. | Throughout | A | | | |
| Detail: Cove Base & Cove Base Adhesive | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M006 | Type: Misc. | Throughout | A | | | |
| Detail: Fire Doors | | | | | | |
| | | | | | | |
| | | | | | | |
| HA ID: M013 | Type: Misc. | Throughout | A | | | |
| Detail: Drywall and Joint Compound | | | | | | |
| | | | | | | |
| | | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| 9 Assessment of Friable and Non-friable Assumed Positive or Tested Positive Materials | | | | | | | |
|---|--|-----|----------|--------------------------------|---------|--|---|
| Homogeneous Material Description | Location(s) | ACM | Friable? | Assessment and Response Action | | | |
| | | | | AHERA Assessment Category | | Management Planner's recommended Response Action | |
| | | | | Prior | Current | Action | Notes/Comments |
| HA ID: M003 Type: Misc. Detail Flooring Materials | Throughout | A | NF | 5 | 5 | O & M | |
| HA ID: M005 Type: Misc. Detail Ceiling tiles | Throughout | Y | F | 7 | 7 | AR | IT appears that the ceiling tiles on the second floor that were tested positive in 2009 may still be present. |
| HA ID: M006 Type: Misc. Detail: Fire Doors | Throughout | A | NF | 5 | 5 | O & M | |
| HA ID: M008 Type: Misc. 12 x 12 Floor Tiles (Various Colors) | Throughout | A | NF | 5 | 5 | O & M | |
| Key to Abbreviations: | | | | | | | |
| Type: | TSI= Thermal Systems Insulation, Surf.= Surfacing Material, Misc.= Miscellaneous Material | | | | | | |
| ACM: | A= Assumed, Y= Determined to be asbestos through sampling. | | | | | | |
| Friable | F= Friable, NF= Non-friable. | | | | | | |
| AHERA Assessment Category: | 1)= Damaged or significantly damaged TSI ACBM, 2)= Damaged friable surfacing ACBM, 3)= Significantly damaged friable surfacing ACBM 4)= Damaged or significantly damaged friable miscellaneous ACBM, 5)= ACBM with potential for damage, 6)= ACBM with potential for significant damage 7)= Any remaining friable ACBM or friable suspected ACBM. (8)= Not applicable (non friable surfacing or miscellaneous material). | | | | | | |
| Response Action: | O&M= Continue surveillance and Operations and Maintenance, AR= Abatement Required as soon as possible. | | | | | | |

Form A: Homogeneous Area Assessment and Response Action Form

| 9 Assessment of Friable and Non-friable Assumed Positive or Tested Positive Materials | | | | | | | | |
|---|--|-------------|-----|----------|--------------------------------|---------|--|------------------|
| Homogeneous Material Description | | Location(s) | ACM | Friable? | Assessment and Response Action | | | |
| | | | | | AHERA Assessment Category | | Management Planner's recommended Response Action | |
| | | | | | Prior | Current | Action | Notes/Comments |
| HA ID: M010 | Type: Misc. | Throughout | A | NF | 5 | 5 | O & M | |
| Detail Mastic under flooring material | | | | | | | | |
| HA ID: M011 | Type: Misc. | Throughout | A | NF | N/A | 5 | O & M | Grout is friable |
| Detail Ceramic tiles & grout | | | | | | | | |
| HA ID: M006 | Type: Misc. | Throughout | A | NF | 5 | 5 | O & M | |
| Detail: Fire Doors | | | | | | | | |
| HA ID: M012 | Type: Misc. | Throughout | A | NF | 5 | 5 | O & M | |
| Detail: Covebase & Covebase adhesive | | | | | | | | |
| Key to Abbreviations: | | | | | | | | |
| Type: | TSI= Thermal Systems Insulation, Surf.= Surfacing Material, Misc.= Miscellaneous Material | | | | | | | |
| ACM: | A= Assumed, Y= Determined to be asbestos through sampling. | | | | | | | |
| Friable | F= Friable, NF= Non-friable. | | | | | | | |
| AHERA Assessment Category: | 1)= Damaged or significantly damaged TSI ACBM, 2)= Damaged friable surfacing ACBM, 3)= Significantly damaged friable surfacing ACBM 4)= Damaged or significantly damaged friable miscellaneous ACBM, 5)= ACBM with potential for damage, 6)= ACBM with potential for significant damage 7)= Any remaining friable ACBM or friable suspected ACBM. (8)= Not applicable (non friable surfacing or miscellaneous material). | | | | | | | |
| Response Action: | O&M= Continue surveillance and Operations and Maintenance, AR= Abatement Required as soon as possible. | | | | | | | |

ACCREDITATION INFORMATION

LEA DESIGNATED PERSON:

Address: 102 Hickory Drive

Bel Air, Maryland 21201

Telephone: (410) 638-4088

Typed Name: Cynthia Yost

Training course (s): AHERA Inspector,
Management Planner, Asbestos Supervisor
See attached training certifications.

Date(s): _____ Total Hrs: _____

Agency: _____

INSPECTIONS, BULK SAMPLING, AND ASSESSMENTS

Inspections were conducted by: Edward Clarke

Date: June 1, thru November 30, 2013

Bulk samples were collected by:

Date:

Assessments were collected by: Edward Clarke

Date: 09/27/13

Signature  _____

Signature _____

Name: Edward Clarke

Name _____

Accreditation photo ID No: 120333

Accreditation/photo ID No _____

State and Date: Maryland, 11/28/13


State and Date: _____


MANAGEMENT PLANNER:

Management plan prepared by:

Recommendation(s) for Response

Actions made by:

Signature:  _____

signature:  _____

Name: Joseph Williamson

Name: Joseph Williamson

Accreditation/photo ID No: 121323

Accreditation/photo ID No: 121323

State and Date: Maryland, 03/01/14

State and Date: Maryland, 03/01/14

CARDNO ATC

9231 RUMSEY ROAD COLUMBIA, MD 21045 (410) 381-0232

CERTIFICATE OF ACHIEVEMENT

AWARDED TO

EDWARD CLARKE

IN RECOGNITION OF SUCCESSFUL COMPLETION OF THE COURSE

ASBESTOS INSPECTOR REVIEW

A 4-HOUR ANNUAL REVIEW PROGRAM OF STUDY PRESENTED IN ACCORDANCE WITH
THE PROVISIONS OF THE U.S. ENVIRONMENTAL PROTECTION AGENCY MODEL
ACCREDITATION PLAN, 40 CFR PART 763, APPENDIX C TO SUBPART E,
FOR ACCREDITATION UNDER TSCA TITLE II.

PRESENTED BY



A handwritten signature in black ink, appearing to read 'Clayton E. Miller'.

120333

CERTIFICATE #

COURSE DIRECTOR
CLAYTON E. MILLER

November 28, 2012

COURSE DATE

November 28, 2012

EXAMINATION DATE

November 28, 2013

EXPIRATION DATE

CARDNO ATC

9231 RUMSEY ROAD COLUMBIA, MD 21045 (410) 381-0232

CERTIFICATE OF ACHIEVEMENT

AWARDED TO

JOSEPH WILLIAMSON

IN RECOGNITION OF SUCCESSFUL COMPLETION OF THE COURSE

ASBESTOS MANAGEMENT PLANNER


A 16-HOUR PROGRAM OF STUDY PRESENTED IN ACCORDANCE WITH THE PROVISIONS OF THE U.S. ENVIRONMENTAL PROTECTION AGENCY MODEL ACCREDITATION PLAN, 40 CFR PART 763, APPENDIX C TO SUBPART E, FOR ACCREDITATION UNDER TSCA TITLE II.

PRESENTED BY

121323

CERTIFICATE #




Clayton E. Miller
COURSE DIRECTOR

February 28-March 1, 2013
COURSE DATES

March 1, 2013
EXAMINATION DATE

March 1, 2014
EXPIRATION DATE

Contents

Cover Letter

Form A: Facility Reinspection Data Summary

Items 1-5 Facility Information
Items 6 Negative Materials Summary
Items 7 Abatement Records Review Listing
Items 8 Suspect ACMB identified during 2013 Reinspection
Items 9 Assessment of Friable and non-friable Assumed Positive or Tested Positive Materials

Form B: Homogeneous Area Assessment and Response Actions

Appendix 1: Signoffs

Appendix 2: Training Records

Appendix 3: Abatement Records

Appendix 4: Supporting Documents



Environmental Services, LLC

CLIENTS' SATISFACTION-A MUST

110-J Warwickshire Ln. Glen Burnie, MD 21061 Phone (443) 597-7951 FAX (410) 589-6131

Mrs. Cyhthia Yost
Environmental Compliance Coordinator
Facilities Management Department
Harford County Public Schools
102 South Hickory Avenue
Bel Air Maryland, 21014

Subject: AHERA 3-Year Re-Inspection Report
Project #13-JHC-013

Dear Mrs. Yost,

MEEMSCO Environmental Services is pleased to provide this report documenting the 3-year re-inspection of friable and non-friable known or assumed asbestos containing building materials (ACMB) we performed from July through November 2013.

The Inspectors 1) conducted a visual re-inspection and reassessment of friable known or assumed ACMB, 2) visually inspected the condition of previously considered non-friable ACMB touched the Material to evaluate whether it had become friable since the last re-inspection, 3) identified homogeneous areas with material that had become friable since the last re-inspection, 4) collected and submitted for analysis of bulk samples of newly friable material that had been assumed to contain ACMB samples collected, and 5) assessed the condition of the newly friable materials in area where samples were collected and of materials assumed to be ACMB.

The following forms and tables list the materials we inspected. If friable materials were observed, an assessment form was completed.

The inspection, bulk samples (if collected) and assessments were completed by the undersigned inspector. The management planner reviewed the inspector's findings and recommended the noted response actions

MEEMSCO reviewed and relied on the previous re-inspection report provided by the client report which is attached, listing material previously identified along with newly identified materials. All were reinspected and assessed. Our recommended response actions are included on the attached forms.

Inaccessible Areas

MEEMSCO attempted to inspect and access all materials previously identified or assumed to be ACMB. No inferences/conclusions/assessments assumption can be made about the condition of ACMB that may exist in wall chases.

Limitations and Exclusions


All professional opinions presented in this report are based solely on the scope of work conducted and sources referred to in our report. The data presented by MEEMSCO in this report was collected and analyzed using generally accepted industry principles and practices at the time the report was generated.

This report represents the conditions, locations, and materials that were observed at the time the field work was conducted. No inferences regarding other conditions, locations, or materials, at a later or earlier time may be made based on the contents of the report, MEEMSCO's liability and that of its contractors and subcontractors arising from any services rendered hereunder, shall not exceed ten (10) percent of the total fee paid by the client to MEEMSCO for this school's three year re-inspection project. No other warranty expressed or implied is made. The accuracy of this report is limited to the accuracy of the information obtained by MEEMSCO from the Harford County Public Schools System.

This report was prepared for the sole use of our client. The use of this report by anyone other than our client or MEEMSCO is strictly prohibited without the expressed prior written consent of MEEMSCO. Portions of this report may not be used independent of the entire report..

If you have any questions regarding this report, please do not hesitate to contact us.

Sincerely,
MEEMSCO Environmental Services



Edward Clarke, President/CEO

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace High

ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089

DATE: 7/8/2010

EPA ACCREDITED INSPECTOR/ACCREDITATION NO.: Charles McEleney MD # 106225

SIGNATURE: _____

EPA MANAGEMENT PLANNER/ACCREDITATION NO.: Charles McEleney MD # 106225

SIGNATURE: _____

PREVIOUSLY IDENTIFIED OR ASSUMED ACM:

| Throughout (including gym) - | Stage - |
|---|-----------------------------|
| 12"x12" floor tile and mastic - 30,000 sf | stage light wiring - 212 lf |
| 9"x9" floor tile and mastic - 600 sf | |
| mudded pipe fittings - 750 | |
| fire doors - 20 | |
| Gym - | |
| vibration collars - 80 sf | |
| pipe insulation - 130 lf | |
| Rooms 156, 159, 160, 162, 167, 227 and 403 - | |
| layered paper pipe insulation - 542 lf | |
| | |
| | |

CHANGES IN MATERIAL CONDITION:

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

Small scale asbestos removal includes abatement of window caulk from Boys Locker Room windows in 2009.

Previous sampling indicates that pipe insulation in 227 is not asbestos-containing. This area will be removed from the asbestos inventory.

Floor tile removed in CR 140 & 143, 136 & 159.

NEWLY IDENTIFIED/SAMPLED MATERIALS:

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 7/8/2010

REMAINING ACM IN BUILDING:

| | |
|---|--|
| Throughout (including gym) - | |
| 12"x12" floor tile and mastic - 30,000 sf | |
| 9"x9" floor tile and mastic - 600 sf | |
| mudded pipe fittings - 750 | |
| fire doors - 20 | |
| Gym - | |
| vibration collars - 80 sf | |
| pipe insulation - 130 lf | |
| Rooms 156, 159, 160, 167 and 403 - | |
| pipe insulation - 542 lf | |
| Stage - | |
| stage light wiring - 212 lf | |
| Science Rooms - | |
| Lab table tops - 1000 sf | |

- mud pipe fittings** - good condition
- pipe insulation** - good condition
- vibration collars** - good condition
- 9"x9" floor tile** - good condition
- 9"x9" floor tile mastic** - good condition
- 12"x12" floor tile** - good condition
- 12"x12" floor tile mastic** - good condition
- stage light wiring** - good condition
- fire doors** - good condition

Mud pipe fittings are present on fiberglass insulated pipes in the gym building as well as above suspended ceiling and inaccessible areas of the main building.

AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
BULK SAMPLE DOCUMENTATION

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 7/8/2010
COLLECTED BY: Charles R. McElaney

| Sample No. | Friable | | Homogeneous Area | Description of Exact Location |
|------------|---------|-----|------------------|-------------------------------|
| | Yes | No | | |
| N/A | | N/A | N/A | N/A |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 7/8/2010
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---|-----------------------------|
| Material Type: <u>Mud Pipe Fittings</u> | Location: <u>throughout</u> |
| Area: <u>Sq. Ft.</u> | Ln. Ft. <u>750 fittings</u> |

COMMENTS (Optional)

Mud pipe fittings on fiberglass insulated piping. Material is accessible in gym and is also found above the suspended ceiling and in inaccessible locations (behind walls) in main building. Accessible material appears to be in good condition.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|-------|
| Significant | _____ |
| Moderate | _____ |
| Light | _____ |
| None | X |

| Water | |
|-----------|-------|
| Extensive | _____ |
| Moderate | _____ |
| Slight | _____ |
| None | X |

| Deterioration | |
|---------------|-------|
| Heavy | _____ |
| Moderate | _____ |
| Light | X |
| None | _____ |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|-------|
| <1 Ft. | _____ |
| 1 to 5 Ft. | _____ |
| Over 5 Ft. | X |

| Accessible | |
|--------------|-------|
| Within Reach | _____ |
| Barely | X |
| Unreachable | _____ |

| Texture | |
|----------|-------|
| Rough | _____ |
| Pitted | _____ |
| Moderate | X |
| Smooth | _____ |

| Adjacent Rooms | |
|----------------|-------|
| Gymnasium | _____ |
| Music Rm. | _____ |
| Mech. Rm. | _____ |
| Elevators | _____ |

AIR FLOW FACTORS

| Barriers | |
|--------------|-------|
| Permanent | _____ |
| Encapsulated | _____ |
| None | X |
| Enclosed | _____ |

| Ventilation | |
|----------------|-------|
| Yes | _____ |
| None | _____ |
| If Yes, Intake | _____ |
| Exhaust | _____ |

| Air Movement | |
|--------------|-------|
| High | _____ |
| Moderate | _____ |
| Low | _____ |

| Air Conduits | |
|--------------|-------|
| Air Plenum | _____ |
| Air Shaft | _____ |
| Elevator | _____ |
| Shaft | _____ |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 7/8/2010
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|--|---|
| Material Type: <u>Pipe Insulation</u> | Location: <u>Gym + Rms 156, 159, 160, 162, 167, 403</u> |
| Area: Sq. Ft. _____ | Ln. Ft. <u>672</u> |

COMMENTS (Optional)
Asbestos pipe insulation is in good condition.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|---------|
| Significant | _____ |
| Moderate | _____ |
| Light | _____ |
| None | _____ X |

| Water | |
|-----------|---------|
| Extensive | _____ |
| Moderate | _____ |
| Slight | _____ |
| None | _____ X |

| Deterioration | |
|---------------|---------|
| Heavy | _____ |
| Moderate | _____ |
| Light | _____ X |
| None | _____ |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|---------|
| <1 Ft. | _____ |
| 1 to 5 Ft. | _____ |
| Over 5 Ft. | _____ X |

| Accessible | |
|--------------|---------|
| Within Reach | _____ |
| Barely | _____ X |
| Unreachable | _____ |

| Texture | |
|----------|---------|
| Rough | _____ |
| Pitted | _____ |
| Moderate | _____ X |
| Smooth | _____ |

| Adjacent Rooms | |
|----------------|-------|
| Gymnasium | _____ |
| Music Rm. | _____ |
| Mech. Rm. | _____ |
| Elevators | _____ |

AIR FLOW FACTORS

| Barriers | |
|--------------|---------|
| Permanent | _____ |
| Encapsulated | _____ |
| None | _____ X |
| Enclosed | _____ |

| Ventilation | |
|----------------|-------|
| Yes | _____ |
| None | _____ |
| If Yes, Intake | _____ |
| Exhaust | _____ |

| Air Movement | |
|--------------|-------|
| High | _____ |
| Moderate | _____ |
| Low | _____ |

| Air Conduits | |
|--------------|-------|
| Air Plenum | _____ |
| Air Shaft | _____ |
| Elevator | _____ |
| Shaft | _____ |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
REINSPECTION SUMMARY TABLE**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 7/8/2010

| Homogeneous Area (#), Type of Materials | Sampled 2007 (Y/N) | Friable 2007 (Y/N) | Changes 2010 (Y/N) | Friable 2010 (Y/N) | Sampled 2010 (Y/N) | AHERA Class. | Response Action | Hazard Rank # | Schedule (Initial - Completion) |
|--|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------|------------------------|----------------------|--|
| Pipe Insulation | N | Y | N | Y | N | 5 | O&M | 2 | Ongoing |
| Mud Pipe Fittings | N | Y | N | Y | N | 5 | O&M | 2 | Ongoing |
| Vibration Collars | N | N | N | N | N | N/A | O&M | 2 | Ongoing |
| 9"x9" Floor Tile and Mastic | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| 12"x12" Floor Tile and Mastic | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| Stage Light Wiring | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| Fire Doors | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| Lab Table Tops | Y | N | N | N | N | N/A | O&M | 1 | Ongoing |

KEY:

Homogeneous Area

T - Thermal System Insulation
 S - Surfacing Material
 M - Miscellaneous

Response Action

RM - Remove
 RP - Repair
 ECP - Encapsulate

O&M - Operations and Maintenance
 ISL - Isolate

C&R Environmental Associates, Inc.
 1415 Bush Street, 2nd Floor
 Baltimore, MD 21230

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update
Resource Evaluation**

FACILITY: Havre De Grace High

ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089

DATE: 7/8/2010

Costs are projected for removing and for repairing and encapsulating the ACMs assessed during the AHERA Building Re-inspection. The cost estimates are based upon unit cost rates for abatement of various ACMs and are provided for general planning purposes only. Many project-specific factors, including economies of scale, contract and schedule requirements, etc. will affect the actual costs for abatement. The cost estimates provided do not include the cost of replacement of the materials removed or for professional Industrial Hygiene Services, such as project design and air monitoring.

The following pages show response action costs, which are based upon an assessment of the potential health hazard as reflected by the hazard ranking. The hazard ranking system derives from the Hazard Potential Algorithm used by the AHERA Building Inspector to assess the condition of ACM and was approved for use in this reinspection by the Harford County Public Schools AHERA designated person.

Generally, the following Hazard Ranking Values initiate the following actions:

| Hazard Ranking | Response Action |
|----------------|---|
| 6 | Schedule for immediate removal. |
| 5 | Schedule for immediate action (repair/encapsulation or removal). |
| 4 | Monitor. Schedule for near term action. |
| 3 | Monitor. Schedule for future removal. |
| 2 | Monitor. As long as ACM condition does not change or use of area in which ACM exists does not change, schedule for removal later when monies are available. |
| 1 | Monitor. Generally no other action is required unless the building is renovated or demolished. |

**AHERA Three (3) Year Reinspection - 2010
Asbestos Management Plan Update**

**Budgetary Costs by Hazard Ranking
Harford County Public Schools**

| Material | Quantity | Repair/ Encapsulate | Remove |
|---|-----------|------------------------|--------------|
| A. Damaged ACM, Hazard Categories 3, 4, 5, 6 | | | |
| <u>Hazard Category 6</u> N/A | | | |
| <u>Hazard Category 5</u> N/A | | | |
| <u>Hazard Category 4</u> N/A | | | |
| <u>Hazard Category 3</u> N/A | | | |
| B. Undamaged ACM, Hazard Categories 1, 2 | | | |
| <u>Hazard Category 2</u> | | | |
| Mud Pipe Fittings | 750 | N/A | \$2,000 |
| Pipe Insulation | 672 lf | N/A | \$13,440 |
| <u>Hazard Category 1</u> | | | |
| 9"x9" floor tile | 600 sf | N/A | \$2,100 |
| 9"x9" floor tile mastic | 600 sf | N/A | \$900 |
| 12"x12" floor tile | 30,000 sf | N/A | \$ 77,000.00 |
| 12"x12" floor tile mastic | 30,000 sf | N/A | \$45,000 |
| Stage Light Wiring | 212 lf | N/A | \$ 636.00 |
| Vibration Collars | 80 sf | N/A | \$ 1,000.00 |
| Fire Doors | 20 | N/A | \$ 6,000.00 |
| Laboratory Table Tops | 1000 sf | N/A | \$10,000 |

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

CHARLES R. MCELENEY

*has met the attendance requirements and successfully completed
the course entitled*

8-Hr EPA AHERA Insp/Mgmt Planner Refresher

For Accreditation Under TSCA Title II.

2/18/2010

Course Date

2/18/2010

Exam Date

2/18/2011

Expiration Date

ROBERTA SPRATT-RITTER

Principal Instructor



106225

Certification No.

VA106225

Virginia Certification No.

E. RUSH BARNETT

Course Director



1331 Ashton Road

P.O. Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
SUMMARY SHEET

FACILITY: Havre De Grace High

ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089

DATE: 9/12/2007

EPA ACCREDITED INSPECTOR/ACCREDITATION NO.: Charles McEleney MD # 086055

SIGNATURE: [Handwritten Signature]

EPA MANAGEMENT PLANNER/ACCREDITATION NO.: Charles McEleney MD # 086055

SIGNATURE: [Handwritten Signature]

PREVIOUSLY IDENTIFIED OR ASSUMED ACM:

Table with 2 columns: Location (Throughout, Gym, Rooms) and Material Description (e.g., 12"x12" floor tile, vibration collars, layered paper pipe insulation). Includes a 'Stage' column for listing specific findings like stage light wiring.

CHANGES IN MATERIAL CONDITION:

Multiple horizontal lines provided for recording changes in material condition.

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

There have been numerous small scale projects for the removal of asbestos floor tile/mastic and window glazing.

Asbestos pipe insulation was not identified in Rm 162. Room 156 was not accessible to assess pipe insulation.

NEWLY IDENTIFIED/SAMPLED MATERIALS:

Science Lab Table tops in rooms 228, 230, 232, 233 and 234 are asbestos containing based on laboratory analysis of sample from Room 233.

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
SUMMARY SHEET**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/12/2007

REMAINING ACM IN BUILDING:

| | |
|--|--|
| Throughout (including gym) - | |
| 12"x12" floor tile and mastic - 30,000 sf | |
| 9"x9" floor tile and mastic - 600 sf | |
| mudded pipe fittings - 750 | |
| fire doors - 20 | |
| Gym - | |
| vibration collars - 80 sf | |
| pipe insulation - 130 lf | |
| Rooms 156, 159, 160, 167, 227 and 403 - | |
| pipe insulation - 542 lf | |
| Stage - | |
| stage light wiring - 212 lf | |
| Science Rooms - | |
| Lab table tops - 1000 sf | |

- mud pipe fittings** - good condition
- pipe insulation** - good condition
- vibration collars** - good condition
- 9"x9" floor tile** - good condition
- 9"x9" floor tile mastic** - good condition
- 12"x12" floor tile** - good condition
- 12"x12" floor tile mastic** - good condition
- stage light wiring** - good condition
- fire doors** - good condition

Mud pipe fittings are present on fiberglass insulated pipes in the gym building as well as above suspended ceiling and inaccessible areas of the main building.

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
BULK SAMPLE DOCUMENTATION**

FACILITY: Havre De Grace High
 ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
 DATE: 9/12/2007
 COLLECTED BY: Charles R. McElaney

| Sample No. | Friable | | Homogeneous Area | Description of Exact Location |
|--------------|---------|----|------------------|-------------------------------|
| | Yes | No | | |
| HGH-1-091207 | | X | Lab Table Top | Room 233 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |



CERTIFICATE OF ANALYSIS

Client: C & R Environmental Associates, Inc.
Address: 1415 Bush Street, 2nd Floor - Suite B
 Baltimore, Maryland 21230

Job Name: Harford County Public Schools
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: Not Provided

Chain Of Custody: 116386
Date Analyzed: 10/25/2007
Person Submitting: Charles McEleney

Attention: Charles McEleney

Page 1 of 2

Summary of Polarized Light Microscopy

| AMA Sample Number | Client Sample # | Total Asbestos | Chrysotile Percent | Amosite Percent | Crocidolite Percent | Other Asbestos Percent | Mineral Wool Percent | Fiberglass Percent | Organic Percent | Synthetic Percent | Other Percent | Particulate Percent | Sample Color | Homogeneity | Analyst ID | Comments |
|-------------------|-----------------|----------------|--------------------|-----------------|---------------------|------------------------|----------------------|--------------------|-----------------|-------------------|---------------|---------------------|--------------|-------------|------------|----------|
| 0805489 | J-1-071307 | NAD | -- | -- | -- | -- | -- | TR | 15 | TR | -- | 85 | Multi | Layered | PC | |
| 0805490 | J-2-071307 | NAD | -- | -- | -- | -- | -- | -- | -- | -- | -- | 100 | Black | Homogeneous | PC | |
| 0805491 | FH-1-080307 | 15 | 13 | 2 | -- | -- | -- | -- | -- | -- | -- | 85 | Black | Homogeneous | PC | |
| 0805492 | FH-2-080307 | NAD | -- | -- | -- | -- | -- | -- | -- | -- | -- | 100 | Black | Homogeneous | PC | |
| 0805493 | EH1-090507 | NAD | -- | -- | -- | -- | -- | -- | -- | -- | -- | 100 | Dk Brown | Homogeneous | PC | |
| 0805494 | HGH-1-091207 | 15 | 13 | 2 | -- | -- | -- | -- | -- | -- | -- | 85 | Black | Homogeneous | PC | |
| 0805495 | AN-1-091207 | 15 | 13 | 2 | -- | -- | -- | -- | -- | -- | -- | 85 | Black | Homogeneous | PC | |
| 0805496 | CMW-1-092107 | 15 | 13 | 2 | -- | -- | -- | -- | -- | -- | -- | 85 | Black | Homogeneous | PC | |
| 0805497 | BAM-1-101207 | NAD | -- | -- | -- | -- | -- | -- | -- | -- | -- | 100 | Black | Homogeneous | PC | |
| 0805498 | BAH-1-101207 | 15 | 13 | 2 | -- | -- | -- | -- | -- | -- | -- | 85 | Black | Homogeneous | PC | |
| 0805499 | SH-1-101807 | NAD | -- | -- | -- | -- | -- | -- | -- | -- | -- | 100 | Black | Homogeneous | PC | |

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

An AIHA (#100470), NVLAP (101143-0), and NY ELAP (#10920) Accredited Laboratory

4475 Forbes Blvd. · Lanham, MD, 20706 · (301) 459-2640 · Toll Free (800) 346-0961 · Fax (301) 459-2643



CERTIFICATE OF ANALYSIS

| | | | | | |
|-------------------|---------------------------------------|----------------------|-------------------------------|---------------------------|------------------|
| Client: | C & R Environmental Associates, Inc. | Job Name: | Harford County Public Schools | Chain Of Custody: | 116386 |
| Address: | 1415 Bush Street, 2nd Floor - Suite B | Job Location: | Not Provided | Date Analyzed: | 10/25/2007 |
| | Baltimore, Maryland 21230 | Job Number: | Not Provided | Person Submitting: | Charles McEleney |
| | | P.O. Number: | Not Provided | | |
| Attention: | Charles McEleney | | | | |

Page 2 of 2

Summary of Polarized Light Microscopy

| AMA Sample Number | Client Sample # | Total Asbestos | Chrysotile Percent | Amosite Percent | Crocidolite Percent | Other Asbestos Percent | Mineral Wool Percent | Fiberglass Percent | Organic Percent | Synthetic Percent | Other Percent | Particulate Percent | Sample Color | Homogeneity | Analyst ID | Comments |
|-------------------|-----------------|----------------|--------------------|-----------------|---------------------|------------------------|----------------------|--------------------|-----------------|-------------------|---------------|---------------------|--------------|-------------|------------|----------|
|-------------------|-----------------|----------------|--------------------|-----------------|---------------------|------------------------|----------------------|--------------------|-----------------|-------------------|---------------|---------------------|--------------|-------------|------------|----------|

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

- TEM RECOMMENDATION** - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos fibers below the resolution limits of optical microscopy.
- MATRIX REDUCTION RECOMMENDATION** - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23

Peerawut Chaikenee

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

An AIHA (#100470), NVLAP (101143-0), and NY ELAP (#10920) Accredited Laboratory

4475 Forbes Blvd. · Lanham, MD, 20706 · (301) 459-2640 · Toll Free (800) 346-0961 · Fax (301) 459-2643

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/12/2007
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---|---|
| Material Type: <u>Mud Pipe Fittings</u> | Location: <u>throughout</u> |
| Area: <u> </u> Sq. Ft. <u> </u> | Ln. Ft. <u> </u> <u>750 fittings</u> |

COMMENTS (Optional)

Mud pipe fittings on fiberglass insulated piping. Material is accessible in gym and is also found above the suspended ceiling and in inaccessible locations (behind walls) in main building. Accessible material appears to be in good condition.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-----------------|------------------------------|
| Significant | <u> </u> |
| Moderate | <u> </u> |
| Light | <u> </u> |
| None | <u> X </u> |

| Water | |
|--------------|------------------------------|
| Extensive | <u> </u> |
| Moderate | <u> </u> |
| Slight | <u> </u> |
| None | <u> X </u> |

| Deterioration | |
|----------------------|--|
| Heavy | <u> </u> |
| Moderate | <u> </u> |
| Light | <u> X </u> |
| None | <u> </u> |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|----------------------------------|------------------------------|
| <1 Ft. | <u> </u> |
| 1 to 5 Ft. | <u> </u> |
| Over 5 Ft. | <u> X </u> |

| Accessible | |
|-------------------|--|
| Within Reach | <u> </u> |
| Barely | <u> X </u> |
| Unreachable | <u> </u> |

| Texture | |
|----------------|--|
| Rough | <u> </u> |
| Pitted | <u> </u> |
| Moderate | <u> X </u> |
| Smooth | <u> </u> |

| Adjacent Rooms | |
|-----------------------|-----------------------------|
| Gymnasium | <u> </u> |
| Music Rm. | <u> </u> |
| Mech. Rm. | <u> </u> |
| Elevators | <u> </u> |

AIR FLOW FACTORS

| Barriers | |
|-----------------|--|
| Permanent | <u> </u> |
| Encapsulated | <u> </u> |
| None | <u> X </u> |
| Enclosed | <u> </u> |

| Ventilation | |
|--------------------|-----------------------------|
| Yes | <u> </u> |
| None | <u> </u> |
| If Yes, Intake | <u> </u> |
| Exhaust | <u> </u> |

| Air Movement | |
|---------------------|-----------------------------|
| High | <u> </u> |
| Moderate | <u> </u> |
| Low | <u> </u> |

| Air Conduits | |
|---------------------|-----------------------------|
| Air Plenum | <u> </u> |
| Air Shaft | <u> </u> |
| Elevator | <u> </u> |
| Shaft | <u> </u> |

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/12/2007
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---------------------------------------|--|
| Material Type: <u>Pipe Insulation</u> | Location: <u>Gym + Rms 156, 159, 160, 162, 167, 227, 403</u> |
| Area: <u> </u> Sq. Ft. | <u> </u> Ln. Ft. <u> </u> 672 |

COMMENTS (Optional)

Suspect asbestos pipe insulation is in good condition. Some very minor deterioration of insulation in Rm 227.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|-------------------|
| Significant | <u> </u> |
| Moderate | <u> </u> |
| Light | <u> </u> |
| None | <u> </u> X |

| Water | |
|-----------|-------------------|
| Extensive | <u> </u> |
| Moderate | <u> </u> |
| Slight | <u> </u> |
| None | <u> </u> X |

| Deterioration | |
|---------------|-------------------|
| Heavy | <u> </u> |
| Moderate | <u> </u> |
| Light | <u> </u> X |
| None | <u> </u> |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|-------------------|
| <1 Ft. | <u> </u> |
| 1 to 5 Ft. | <u> </u> |
| Over 5 Ft. | <u> </u> X |

| Accessible | |
|--------------|-------------------|
| Within Reach | <u> </u> |
| Barely | <u> </u> X |
| Unreachable | <u> </u> |

| Texture | |
|----------|-------------------|
| Rough | <u> </u> |
| Pitted | <u> </u> |
| Moderate | <u> </u> X |
| Smooth | <u> </u> |

| Adjacent Rooms | |
|----------------|-----------------|
| Gymnasium | <u> </u> |
| Music Rm. | <u> </u> |
| Mech. Rm. | <u> </u> |
| Elevators | <u> </u> |

AIR FLOW FACTORS

| Barriers | |
|--------------|-------------------|
| Permanent | <u> </u> |
| Encapsulated | <u> </u> |
| None | <u> </u> X |
| Enclosed | <u> </u> |

| Ventilation | |
|----------------|-----------------|
| Yes | <u> </u> |
| None | <u> </u> |
| If Yes, Intake | <u> </u> |
| Exhaust | <u> </u> |

| Air Movement | |
|--------------|-----------------|
| High | <u> </u> |
| Moderate | <u> </u> |
| Low | <u> </u> |

| Air Conduits | |
|--------------|-----------------|
| Air Plenum | <u> </u> |
| Air Shaft | <u> </u> |
| Elevator | <u> </u> |
| Shaft | <u> </u> |

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
REINSPECTION SUMMARY TABLE**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/12/2007

| Homogeneous Area (#), Type of Materials | Sampled 2004 (Y/N) | Friable 2004 (Y/N) | Changes 2007 (Y/N) | Friable 2007 (Y/N) | Sampled 2007 (Y/N) | AHERA Class. | Response Action | Hazard Rank # | Schedule (Initial - Completion) |
|--|--------------------|--------------------|--------------------|--------------------|--------------------|--------------|-----------------|---------------|---------------------------------|
| Pipe Insulation | N | Y | N | Y | N | 5 | O&M | 2 | Ongoing |
| Mud Pipe Fittings | N | Y | N | Y | N | 5 | O&M | 2 | Ongoing |
| Vibration Collars | N | N | N | N | N | N/A | O&M | 2 | Ongoing |
| 9"x9" Floor Tile and Mastic | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| 12"x12" Floor Tile and Mastic | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| Stage Light Wiring | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| Fire Doors | N | N | N | N | N | N/A | O&M | 1 | Ongoing |
| Lab Table Tops | N/A | N/A | N/A | N | N | N/A | O&M | 1 | Ongoing |

KEY:

Homogeneous Area

T - Thermal System Insulation
 S - Surfacing Material
 M - Miscellaneous

Response Action

RM - Remove
 RP - Repair
 ECP - Encapsulate

O&M - Operations and Maintenance
 ISL - Isolate

C&R Environmental Associates, Inc.
 1415 Bush Street, 2nd Floor
 Baltimore, MD 21230

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update
Resource Evaluation**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/12/2007

Costs are projected for removing and for repairing and encapsulating the ACMs assessed during the AHERA Building Re-inspection. The cost estimates are based upon unit cost rates for abatement of various ACMs and are provided for general planning purposes only. Many project-specific factors, including economies of scale, contract and schedule requirements, etc. will affect the actual costs for abatement. The cost estimates provided do not include the cost of replacement of the materials removed or for professional Industrial Hygiene Services, such as project design and air monitoring.

The following pages show response action costs, which are based upon an assessment of the potential health hazard as reflected by the hazard ranking. The hazard ranking system derives from the Hazard Potential Algorithm used by the AHERA Building Inspector to assess the condition of ACM and was approved for use in this reinspection by the Harford County Public Schools AHERA designated person.

Generally, the following Hazard Ranking Values initiate the following actions:

| Hazard Ranking | Response Action |
|-----------------------|---|
| 6 | Schedule for immediate removal. |
| 5 | Schedule for immediate action (repair/encapsulation or removal). |
| 4 | Monitor. Schedule for near term action. |
| 3 | Monitor. Schedule for future removal. |
| 2 | Monitor. As long as ACM condition does not change or use of area in which ACM exists does not change, schedule for removal later when monies are available. |
| 1 | Monitor. Generally no other action is required unless the building is renovated or demolished. |

**AHERA Three (3) Year Reinspection - 2007
Asbestos Management Plan Update**

**Budgetary Costs by Hazard Ranking
Harford County Public Schools**

| Material | Quantity | Repair/ Encapsulate | Remove |
|---|-----------|------------------------|--------------|
| A. Damaged ACM, Hazard Categories 3, 4, 5, 6 | | | |
| <u>Hazard Category 6</u> N/A | | | |
| <u>Hazard Category 5</u> N/A | | | |
| <u>Hazard Category 4</u> N/A | | | |
| <u>Hazard Category 3</u> N/A | | | |
| B. Undamaged ACM, Hazard Categories 1, 2 | | | |
| <u>Hazard Category 2</u> | | | |
| Mud Pipe Fittings | 750 | N/A | \$2,000 |
| Pipe Insulation | 672 lf | N/A | \$13,440 |
| <u>Hazard Category 1</u> | | | |
| 9"x9" floor tile | 600 sf | N/A | \$2,100 |
| 9"x9" floor tile mastic | 600 sf | N/A | \$900 |
| 12"x12" floor tile | 30,000 sf | N/A | \$ 77,000.00 |
| 12"x12" floor tile mastic | 30,000 sf | N/A | \$45,000 |
| Stage Light Wiring | 212 lf | N/A | \$ 636.00 |
| Vibration Collars | 80 sf | N/A | \$ 1,000.00 |
| Fire Doors | 20 | N/A | \$ 6,000.00 |
| Laboratory Table Tops | 1000 sf | N/A | \$10,000 |

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

CHARLES R. MCELENEY

*has met the attendance requirements and successfully completed
the course entitled*

8-Hr EPA AHERA Insp/Mgmt Planner Refresher

For Accreditation Under TSCA Title II.

10/2/2007

Course Date

10/2/2007


Exam Date

10/1/2008

Expiration Date

ROBERTA SPRATT-RITTER

Principal Instructor



92527

Certification No.

VA92527

Virginia Certification No.

E. RUSH BARNETT

Course Director



1331 Ashton Road

P.O. Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

MEMORANDUM

2209 Conowingo Road, Bel Air MD 21015 410.638.4088 FAX:410.638.4205

To: All Principals

From: Laura M. Paligo
Environmental Compliance Coordinator

Subject: Reinspections for AHERA Compliance

Date: August 23, 2004

The Asbestos Hazard Emergency Response Act (AHERA) requires all Local Education Agencies (LEAs) to complete inspections that identify asbestos containing materials (ACM) in all school buildings. Results of the inspection must then be compiled in a Management Plan to instruct building occupants, maintenance staff, parents, and any other interested parties how to safely and effectively manage any asbestos identified during the inspection.

Following the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens, and McCoy conducted the initial inspection for most of the schools in Harford County. The first reinspection was performed in 1992 by I-TEM, Ltd. The next reinspections were performed in 1995 by Testwell Craig Testing Laboratories, Inc., 1998 by Brook Environmental and Engineering Corporation, and 2001 by Jenkins Environmental Inc. This year's reinspection will be performed by C & R Environmental, Inc.

The reinspections involve visual inspection, collecting samples of some building materials for analysis, and updating management plans. Any samples taken will be small and the sample locations will be patched. The on site work will require several days at each building. Activities connected with the reinspections will require contractor personnel to work in the school building during regular school hours and some evening hours. Scheduling will require cooperation between the school, contractor, and Facilities Department personnel.

Site work will begin around August 17, 2004. You will receive the school's copy of the reinspection report as it becomes available. Each site will be notified as the details in scheduling are finalized. Please inform building occupants of the upcoming activities. Please call me at ext. 4088 if you have any questions.

pc: Patti Jo Beard

ASHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
SUMMARY SHEET

FACILITY: Havre De Grace High

ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089

DATE: 9/28/2004

EPA ACCREDITED INSPECTOR/ACCREDITATION NO.: Charles McEleney MD # 75043

SIGNATURE: [Handwritten Signature]

EPA MANAGEMENT PLANNER/ACCREDITATION NO.: Charles McEleney MD # 75043

SIGNATURE: [Handwritten Signature]

PREVIOUSLY IDENTIFIED OR ASSUMED ACM:

Table with 2 columns: Location (Throughout, Gym, Rooms) and Material Description (e.g., 12"x12" floor tile, stage light wiring, vibration collars).

CHANGES IN MATERIAL CONDITION:

None

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

[Blank lines for additional comments]

NEWLY IDENTIFIED/SAMPLED MATERIALS:

Throughout - composite wooden fire doors

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
BULK SAMPLE DOCUMENTATION**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/28/2004
COLLECTED BY: NO BULK SAMPLES COLLECTED

| Sample No. | Friable | | Homogeneous Area | Description of Exact Location |
|------------|---------|-----|------------------|-------------------------------|
| | Yes | No | | |
| N/A | N/A | N/A | N/A | N/A |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
HOMOGENEOUS AREA ASSESSMENT**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/28/2004
INSPECTOR: Charles McEleney
SAMPLE ID: N/A

| | |
|---|--|
| Material Type: <u>Pipe Insulation</u> | Location: <u>Gym + Rms 156, 159, 160, 162, 167, 227, 403</u> |
| Area: <u> </u> Sq. Ft. <u> </u> | Ln. Ft. <u>672</u> |

COMMENTS (Optional)

Suspect asbestos pipe insulation is in good condition. Some very minor deterioration of insulation in Rm 227 and 159.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| Physical | |
|-------------|-----------------|
| Significant | <u> </u> |
| Moderate | <u> </u> |
| Light | <u> </u> |
| None | <u>X</u> |

| Water | |
|-----------|-----------------|
| Extensive | <u> </u> |
| Moderate | <u> </u> |
| Slight | <u> </u> |
| None | <u>X</u> |

| Deterioration | |
|---------------|-----------------|
| Heavy | <u> </u> |
| Moderate | <u> </u> |
| Light | <u>X</u> |
| None | <u> </u> |

DISTURBANCE FACTORS

| Proximity to Repair Items | |
|---------------------------|-----------------|
| <1 Ft. | <u> </u> |
| 1 to 5 Ft. | <u> </u> |
| Over 5 Ft. | <u>X</u> |

| Accessible | |
|--------------|-----------------|
| Within Reach | <u> </u> |
| Barely | <u>X</u> |
| Unreachable | <u> </u> |

| Texture | |
|----------|-----------------|
| Rough | <u> </u> |
| Pitted | <u> </u> |
| Moderate | <u>X</u> |
| Smooth | <u> </u> |

| Adjacent Rooms | |
|----------------|-----------------|
| Gymnasium | <u> </u> |
| Music Rm. | <u> </u> |
| Mech. Rm. | <u> </u> |
| Elevators | <u> </u> |

AIR FLOW FACTORS

| Barriers | |
|--------------|-----------------|
| Permanent | <u> </u> |
| Encapsulated | <u> </u> |
| None | <u>X</u> |
| Enclosed | <u> </u> |

| Ventilation | |
|----------------|-----------------|
| Yes | <u> </u> |
| None | <u> </u> |
| If Yes, Intake | <u> </u> |
| Exhaust | <u> </u> |

| Air Movement | |
|--------------|-----------------|
| High | <u> </u> |
| Moderate | <u> </u> |
| Low | <u> </u> |

| Air Conduits | |
|--------------|-----------------|
| Air Plenum | <u> </u> |
| Air Shaft | <u> </u> |
| Elevator | <u> </u> |
| Shaft | <u> </u> |

**AHERA Three (3) Year Reinspection - 2004
Asbestos Management Plan Update
Resource Evaluation**

FACILITY: Havre De Grace High
ADDRESS: 700 Congress Avenue, Havre De Grace, Maryland 21078-3089
DATE: 9/28/2004

Costs are projected for removing and for repairing and encapsulating the ACMs assessed during the AHERA Building Re-inspection. The cost estimates are based upon unit cost rates for abatement of various ACMs and are provided for general planning purposes only. Many project-specific factors, including economies of scale, contract and schedule requirements, etc. will affect the actual costs for abatement. The cost estimates provided do not include the cost of replacement of the materials removed or for professional Industrial Hygiene Services, such as project design and air monitoring.

The following pages show response action costs, which are based upon an assessment of the potential health hazard as reflected by the hazard ranking. The hazard ranking system derives from the Hazard Potential Algorithm used by the AHERA Building Inspector to assess the condition of ACM and was approved for use in this reinspection by the Harford County Public Schools AHERA designated person.

Generally, the following Hazard Ranking Values initiate the following actions:

| Hazard Ranking | Response Action |
|----------------|---|
| 6 | Schedule for immediate removal. |
| 5 | Schedule for immediate action (repair/encapsulation or removal). |
| 4 | Monitor. Schedule for near term action. |
| 3 | Monitor. Schedule for future removal. |
| 2 | Monitor. As long as ACM condition does not change or use of area in which ACM exists does not change, schedule for removal later when monies are available. |
| 1 | Monitor. Generally no other action is required unless the building is renovated or demolished. |

AEROSOL MONITORING & ANALYSIS, INC.

THIS IS TO CERTIFY THAT

CHARLES R. MCELENEY

HAS MET THE ATTENDANCE REQUIREMENTS AND SUCCESSFULLY COMPLETED
THE COURSE ENTITLED

8-HR EPA AHERA INSP/MGMT PLANNER RECERTIFICATION

For Accreditation Under TSCA Title II.

7/9/2004

COURSE DATE

E. RUSH BARNETT

COURSE DIRECTOR

E. Rush Barnett

7/9/2005

EXPIRATION DATE

MD-074053

CERTIFICATE NO.

7/9/2004

EXAM DATE

1331 Ashton Road

P.O. Box 646

Hanover, MD 21076

410-684-3327

FAX: 410-684-3724

MEMORANDUM

2209 Conowingo Road Bel Air MD 21015 410.638.4088 FAX:410.638.4205

To: All Principals
From: Laura M. Paligo
Environmental Compliance Coordinator
Subject: Reinspections for AHERA Compliance
Date: December 19, 2001

The Asbestos Hazard Emergency Response Act (AHERA) requires all Local Education Agencies (LEAs) to complete inspections that identify asbestos containing materials (ACM) in all school buildings. Results of the inspection must then be compiled in a Management Plan to instruct building occupants, maintenance staff, parents, and any other interested parties how to safely and effectively manage any asbestos identified during the inspection.

Following the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens, and McCoy conducted the initial inspection for most of the schools in Harford County. The first reinspection was performed in 1992 by I-TEM, Ltd. The next reinspections were performed in 1995 by Testwell Craig Testing Laboratories, Inc. and in 1998 by Brook Environmental and Engineering Corporation. This year's reinspection will be conducted by Jenkins Environmental Inc.

The reinspections involve visual inspection, collecting samples of some building materials for analysis, and updating management plans. Any samples taken will be small and the sample locations will be patched. The on site work will require several days at each building. Activities connected with the reinspections will require contractor personnel to work in the school building during regular school hours and some evening hours. Scheduling will require cooperation between the school, contractor, and Facilities Department personnel.

Site work will begin around December 19, 2001 and will continue through early next year. You will receive the school's copy of the reinspection report as it becomes available. Each site will be notified as the details in scheduling are finalized. Please inform building occupants of the upcoming activities. Please call me at ext. 4088 if you have any questions.

pc: Patti Jo Beard
Jeffrey C. Ayers

**AHERA Three (3) Year Re-inspection Form
AHERA Management Plan Update**

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

1. Facility:

2. Address:

3. Date:

4. EPA Accred. Insp.:

 (print) Signature:
 (sign)

5. Accreditation Number: State: Date of Expiration:

SECTION 1.0 PREVIOUS INSPECTION REPORT EVALUATION

**TABLE 1.01
PREVIOUSLY IDENTIFIED AND/OR ASSUMED ACM**
 (All materials are assigned "reference numbers" per Table 3.01 ACM ABATEMENT COST ESTIMATE FORM)

| Ref. No. | Material Description | Location | Quantity |
|----------|-------------------------|------------------------------|-----------|
| 16 | vibration collars | gym | 80 SF |
| 5 | layered pipe insulation | Room 162, 167, 227, 160, 159 | 150 LF |
| 12 | mudded pipe fittings | throughout | 750 |
| 3 | tank insulation | gym | 600 SF |
| 8 | 9" floor tile | throughout | 600 SF |
| 9 | 9" floor tile mastic | throughout | 600 SF |
| 10 | 12" floor tile | throughout | 22,000 SF |
| 11 | 12" floor tile mastic | throughout | 30,000 SF |
| 24 | stage light wiring | stage | 212 LF |
| | | | |

AHERA Three (3) Year Re-inspection Form
 AHERA Management Plan Update

Havre De Grace H.S.
 (Facility)

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

TABLE 1.02
CHANGES IN MATERIAL CONDITION

| Ref. No. | Material Description | Location | Quantity | Comments |
|----------|----------------------|-----------------|----------|-----------------------|
| 3 | tank insulation | gym | 600 SF | abated 1999 |
| 16 | vibration collars | gym | 80 SF | changed from 12 LF |
| 12 | mudded pipe fittings | throughout | 750 | earlier 250 (assumed) |
| 5 | pipe insulation | industrial arts | 542 SF | changed from 150 LF |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

- 162 ladie's restroom - no pipe insulation found but noted in earlier report to be present
- tank insulation abated in 1999 - none present
- bulk samples taken of pipe insulation (2) 01, 02 - negative
- bulk samples taken of perforated ceiling material 03 - negative

AHERA Three (3) Year Re-inspection Form
 AHERA Management Plan Update

Havre De Grace H.S.
 (Facility)

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

SECTION 2.0 CURRENT CONDITIONS REPORT

TABLE 2.01
NEWLY IDENTIFIED/SAMPLED ACM MATERIALS
 (Only samples testing positive for asbestos content are reported in Table 2.01)

| Ref. No. | Sample No. ¹ | Material Description | Location | Quantity |
|----------|-------------------------|----------------------|---------------------------|----------|
| 5 | 01 | pipe insulation | room 156 shop (non-ACM) | |
| 5 | 02 | pipe insulation | room 227 (non-ACM) | |
| 27 | 03 | ceiling material | industrial arts (non-ACM) | |
| 5 | | pipe insulation | gym | 130 LF |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

1. Chain-of-Custody forms and Certificates of Analysis are attached.

ADDITIONAL COMMENTS:

- HDGHS - 01 - bulk taken of damaged pipe insulation in shop storage room (156) (negative)
- HDGHS - 02 - bulk taken of damaged pipe insulation in janitor's closet by room 227 (negative)
- HDGHS - 03 - bulk taken of ceiling material in shop wing corridor (negative)

**AHERA Three (3) Year Re-inspection Form
AHERA Management Plan Update**

Havre De Grace H.S.
(Facility)

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

**TABLE 2.02
ACM MATERIALS REMAINING IN BUILDING**

| Ref. No. | Material Description | Location | Quantity | ACM Condition |
|----------|-----------------------|-------------------------|-----------|---------------|
| 16 | vibration collars | gym | 80 SF | good |
| 5 | pipe insulation | gym | 130 LF | good |
| 12 | mudded pipe fittings | throughout | 750 EA | good |
| 8 | 9" floor tile | gym | 600 SF | good |
| 9 | 9" floor tile mastic | throughout | 600 SF | good |
| 10 | 12" floor tile | throughout | 22,000 SF | good |
| 11 | 12" floor tile mastic | throughout | 30,000 SF | good |
| 24 | stage light wiring | stage | 212 LF | good |
| 5 | pipe insulation | 162, 167, 227, 160, 159 | 542 LF | good |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

RECOMMENDED ACTION(S):

test Ref # 5 pipe insulation - tested negative in 2002, but tested positive in 1992 . Retest and confirm - Repair as necessary if possible.

Table 3.0 ABATEMENT COST ESTIMATE REPORT

| REF # | HOMOGENEOUS MATERIAL DESCRIPTIONS | Class. (1) | Quantity | Cost Estimates |
|-----------------------|-----------------------------------|------------|--|----------------|
| 1 | Boiler Insulation (SF) | T | 0.00 | \$0.00 |
| 2 | Breeching Insulation (SF) | T | 0.00 | \$0.00 |
| 3 | Tank Insulation (SF) | T | 0.00 | \$0.00 |
| 4 | Duct Insulation (SF) | T | 0.00 | \$0.00 |
| 5 | Pipe Insulation (LF) | T | 672.00 | \$8,400.00 |
| 6 | Converter (SF) | T | 0.00 | \$0.00 |
| 7 | Sprayed On Insulation (SF) | S | 0.00 | \$0.00 |
| 8 | 9" Floor Tile (SF) | M | 600.00 | \$2,100.00 |
| 9 | 9" Floor Tile Mastic (SF) | M | 600.00 | \$900.00 |
| 10 | 12" Floor Tile (SF) | M | 22,000.00 | \$77,000.00 |
| 11 | 12" Floor Tile Mastic (SF) | M | 30,000.00 | \$45,000.00 |
| 12 | Mudded Pipe Fittings (ea) | T | 750.00 | \$18,750.00 |
| 13 | Fire Doors (ea) | M | 0.00 | \$0.00* |
| 14 | Exterior Transite (SF) | M | 0.00 | \$0.00 |
| 15 | Suspect Asbestos Debris (SF) | T | 0.00 | \$0.00 |
| 16 | Vibration Collars (LF) | T | 80.00 | \$1,600.00 |
| 17 | 2 X 4 Drop Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 18 | 2 X 2 Drop Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 19 | Spline Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 20 | 1' X 1' Glued Ceiling Tile (SF) | M | 0.00 | \$0.00 |
| 21 | Glue spots (SF) | M | 0.00 | \$0.00 |
| 22 | Unit Ventilator Insulation (SF) | T | 0.00 | \$0.00 |
| 23 | Roof Drain Fittings (ea) | M | 0.00 | \$0.00 |
| 24 | Stagelight Wiring (LF) | M | 212.00 | \$636.00* |
| 25 | Porticos (SF) | M | 0.00 | \$0.00 |
| 26 | Gasket Material (LF) | M | 0.00 | \$0.00* |
| 27 | Panel Board Ceiling Material (SF) | M | 0.00 | \$0.00 |
| 28 | | | 0.00 | \$0.00 |
| 29 | | | 0.00 | \$0.00 |
| 30 | | | 0.00 | \$0.00 |
| 31 | | | 0.00 | \$0.00 |
| 32 | | | 0.00 | \$0.00 |
| 33 | | | 0.00 | \$0.00 |
| 34 | | | 0.00 | \$0.00 |
| 35 | | | 0.00 | \$0.00 |
| 36 | | | 0.00 | \$0.00 |
| 37 | | | 0.00 | \$0.00 |
| 38 | | | 0.00 | \$0.00 |
| 39 | | | 0.00 | \$0.00 |
| | | | Total Cost of Full ACM Removal From School | |
| | | | 0.00 | \$154,386.00 |
| bestos Classification | | | | |
| M | Miscellaneous Materials | | | |
| T | Thermal System Insulation (TSI) | | | |
| S | Surfacing Material | | | |

* 1.0 = quantity unknown, default value = \$1000

School: Havre De Grace High School
Address: 700 Congress Avenue
Havre De Grace, MD 21078-3089
Date of Inspection: August 7, 1998

SECTIONS

SECTION 1.0 ACCREDITATION INFORMATION

SECTION 2.0 HARFORD SUMMARY FORM

SECTION 3.0 BROOK ADDENDUM SUMMARY FORM

**SECTION 4.0 HOMOGENOUS AREA ASSESSMENT TABLE AND
FRIABLE HOMOGENOUS AREA ASSESSMENT LOG**

SECTION 5.0 LABORATORY RESULTS

SECTION 6.0 CERTIFICATIONS

SECTION 7.0 ATTACHMENTS

- A. Response Action Determination**
- B. Operations and Maintenance Program**
- C. AHERA Classifications**
- D. Decision Tree**
- E. Glossary**

SECTION 1.0

Brook Environmental & Engineering Corporation Accreditation

Brook Environmental & Engineering Corporation (Brook) accredited personnel performed this re-inspection, collected bulk samples (if necessary), provided the assessments and response action recommendations for Harford County Public Schools.

Inspections, Bulk Sampling, and Assessments


- Re-inspections were conducted by: Beth L. Schmuter
- Bulk Samples were collected by: N/A
- Assessments were made by: Beth L. Schmuter

Management Planner


- Recommendations for Response Actions made by: Brian J. Hug

Personnel

Name: Beth L. Schmuter
Title: Asbestos Inspector
Accreditation Number/ State: 035521/ Maryland
Date of Expiration: August 10, 1999

Signature: 

Name: Brian J. Hug
Title: Management Planner
Accreditation Number/ State: 035323/ Maryland
Date of Expiration: June 5, 1999


Signature: 

2.0 HARFORD COUNTY SUMMARY FORM

AHERA Three (3) Year Re-inspection Form AHERA Management Plan Update

SUMMARY FORM

This form is to be included in the record keeping section of the LEA-designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

1. Facility: Havre De Grace High School
2. Address: 700 Congress Ave., Havre De Grace, Maryland 21078-3089
3. Date: August 7, 1998
4. EPA Accredited Inspector(s): Beth L. Schmuter
5. Signature(s): 
6. Previously Identified and/ or assumed ACM (All materials are assigned "material numbers"):
 - (1) Gymnasium Bldg.-Boiler Room- Tank Insulation, approx. 600 S.F.
 - (2) Throughout Bldg.- Pipe fitting on F.G. insul. Pipe, approx. 250 each
 - (3) Throughout Bldg.-9"x 9" Floor Tile, 600 S.F.
 - (4) Throughout Bldg.-1'X1' Floor Tile, approx. 22,000 S.F.
 - (5) Throughout Bldg.- Floor Tile Mastic, approx. 30,000 S.F.
 - (6) Auditorium- Stage Light Wire Insulation- 212 L.F.

(7) Rooms 159,160,162,167,227, and 403-Fittings on Layered Paper Pipe Insulation-75
EA.

(8) Gymnasium-Flexible connectors

(9) Rooms 159, 160, 162, 167, 227 and 403- Layered Paper Insulation, approx. 150 L.F.

(10)Boiler Gaskets

7. Changes in Material Condition (By material number):

(1) - (9) None

(10) The gasket on the Auditorium Boiler is damaged.

8. Additional Comments/ Abatement Projects:

During the re-inspection, a contractor was prepping the Gymnasium Building boiler room and erecting the decon to remove the 600 S.F. of tank insulation and seven adjacent fittings. The tank insulation is being removed because of leaks in the tank. The Tank insulation appeared to be in good condition. The two (2) pipe fittings reported in bad condition in a previous asbestos inspection were already removed.

In room 159, the pipe fittings and layered pipe insulation were replaced with fiberglass.

9. Newly Identified/ Sampled Materials (All new materials are assigned the next highest available material number):

None

10. Remaining ACM in Building (Section 6 minus Section 7 materials, plus Section 9 materials):

a. Previously Identified Materials:

(1) Gym Bldg.-Boiler Room- Tank Insulation, approx. 600 S.F.

(2) Throughout Bldg.- Pipe fitting on F.G. insul. Pipe, approx. 250 each

(3) Throughout Bldg.-9"x 9" Floor Tile, 600 S.F.

(4) Throughout Bldg.-1'X1' Floor Tile, approx. 22,000 S.F.

(5) Throughout Bldg.- Floor Tile Mastic, approx. 30,000 S.F.

(6) Auditorium- Stage Light Wire Insulation- 212 L.F.

(7) Rooms 160, 162, 167, 227, and 403-Fittings on Layered Paper Pipe Insulation-65
EA.

(8) Gymnasium-Flexible connectors

(9) Rooms 160, 162, 167, 227, and 403- Layered Paper Insulation, approx. 125 L.F.
Remains.

(10)Boiler Gaskets

b. Newly Identified Materials

None

3.0 BROOK ADDENDUM SUMMARY FORM

AHERA Classification Section

| | |
|--------------------------------------|---|
| (1) Tank Insulation | 5 ACBM with potential for damage. |
| (2) Pipe fitting on F/G Pipe | 5 ACBM with potential for damage. |
| (3) 9"x 9" Floor Tile | 8 Non-Friable Surfacing or Miscellaneous ACM. |
| (4) 1'x 1' Floor Tile | 8 Non-Friable Surfacing or Miscellaneous ACM. |
| (5) Floor Tile Mastic | 8 Non-Friable Surfacing or Miscellaneous ACM. |
| (6) Stage Light Wire Insulation | 8 Non-Friable Surfacing or Miscellaneous ACM. |
| (7) Fittings on Layered Paper Insul. | 5 ACBM with potential for damage. |
| (8) Flexible connectors | 8 Non-Friable Surfacing or Miscellaneous ACM. |
| (9) Layered Paper Insulation | 5 ACBM with potential for damage. |
| (10)Boiler Gasket | 8 Non-Friable Surfacing or Miscellaneous ACM. |
| (11)Auditorium Boiler Interior | 1 Damaged or significantly damaged TSI. |
| (All other Boiler Interior) | 5 ACBM with potential for damage. |

Homogenous Area Assessment

(1) Tank Insulation:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

(2) Pipe fitting on F.G. Insulated Pipe:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

(3) 9"x 9" Floor Tile:

Response Action 8: Continue O&M until major renovation or demolition requires removal under the EPA NESHAPs. Or until hazard assessment factors change.

(4) 1'x 1' Floor Tile:

Response Action 8: Continue O&M until major renovation or demolition requires removal under the EPA NESHAPs. Or until hazard assessment factors change.

(5) Floor Tile Mastic:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

(6) Stage Light Wire Insulation:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

(7) Fittings on Layered Paper Pipe Insulation:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

(8) Flexible connectors:

Response Action 8: Continue O&M until major renovation or demolition requires removal under the EPA NESHAPs. Or until hazard assessment factors change.

(9) Layered Paper Insulation:

Response Action 8: Continue with O&M program and take preventive measures to reduce disturbance.

(10) Auditorium Boiler Gasket:

Response Action 5: Continue O&M program and schedule removal when practical and cost effective. (All other Boiler Gasket- **Response Action 8:** Continue O&M until major renovation or demolition requires removal under the EPA NESHAPs. Or until hazard assessment factors change.)

(11) Auditorium Boiler Interior (exposed refractory):

Response Action 5: Repair ACM, Continue with O&M program. (all other Boiler Interior: **Response Action 8:** Continue with O&M program and take preventive measures to reduce disturbance.)

This facility, Havre de Grace High School contains ACM.

The Facility shall be re-inspected by an AHERA accredited inspector by August of 2001, and every three years thereafter until all materials, known or assumed to be ACM, have been removed.

4.0 HOMOGENOUS AREA ASSESSMENT TABLE

AND

FRIABLE HOMOGENOUS AREA ASSESSMENT LOGS

Homogenous Area Assessment Table

School: LAURE DE GRACE HIGH

| Homogenous Area (#), Type of Material | Sampled 1994-95 (Y/N) | Friable 1994-95 (Y/N) | Changes 1998 (Y/N) | Friable 1998 (Y/N) | Sampled 1998 (Y/N) | AHERA Class. | Response Action | Res. Act. # | Schedule (Initial - Completion) |
|--|-----------------------|-----------------------|---|--------------------|--------------------|--------------|-----------------|-------------|---------------------------------|
| ① BOILER TANK INSULATION GYM BUILDING (T) | N | Y | DURING INSPECTION CONTRACTOR PREPPING AREA. REMOVING GOOSE OF TANK INSULATION AND 7 FITTINGS. THE 2 FITTINGS REPORTEDLY IN POOR CONDITION WERE REMOVED. | Y | N | 5 | Otm | 8 | 8/7/98 to Removal |
| ② THROUGHOUT BLDG. PIPE FITTINGS ON F.G. INSUL. PIPE (T) | N | Y | N | Y | N | 5 | Otm | 8 | 8/7/98 to Removal |
| ③ THROUGHOUT BLDG. 9"x9" FLOOR TILE (M) | N | N | N | N | N | 8 | Otm | 8 | 8/7/98 to Removal |

Key: Classifications: Please See Attachment

Homogenous Area

- T - Thermal System Insulation
- S - Surfacing Material
- M - Miscellaneous

Response Action

- RM - Remove
- RP - Repair
- ECP - Encapsulate
- O&M - Operations and Management
- ISL - Isolate

① CONTRACTOR REMOVING TANK INSULATION BECAUSE THE TANKS ARE LEAKING. THE TANK INSULATION IS IN GOOD CONDITION.

Homogenous Area Assessment Table

School: HARE DE GRACE HIGH

| Homogenous Area (#), Type of Material | Sampled 1994-95 (Y/N) | Friable 1994-95 (Y/N) | Changes 1998 (Y/N) | Friable 1998 (Y/N) | Sampled 1998 (Y/N) | AHERA Class. | Response Action | Res. Act. # | Schedule (Initial - Completion) |
|---|-----------------------|-----------------------|--------------------|--------------------|--------------------|--------------|-----------------|-------------|---------------------------------|
| ④ THROUGHOUT BLDG, 1x1' FLOOR TILE (M) | N | N | N | N | N | 8 | O+m | 8 | 8/7/98 to Removal |
| ⑤ THROUGHOUT BLDG. FLOOR TILE MASTIC (m) | N | N | N | N | N | 8 | O+m | 8 | 8/7/98 to Removal |
| ⑥ Auditorium, STAGE LIGHT WARE INSULATION. (M) | N | N | N | N | N | 8 | O+m | 8 | 8/7/98 to Removal |

Key: Classifications: Please See Attachment

Homogenous Area

- T - Thermal System Insulation
- S - Surfacing Material
- M - Miscellaneous

Response Action

- RM - Remove
- RP - Repair
- ECP - Encapsulate
- O&M - Operations and Management
- ISL - Isolate

Homogenous Area Assessment Table

School: HAYNE DE GRACE HIGH

| Homogenous Area (#), Type of Material | Sampled 1994-95 (Y/N) | Friable 1994-95 (Y/N) | Changes 1998 (Y/N) | Friable 1998 (Y/N) | Sampled 1998 (Y/N) | AHERA Class. | Response Action | Res. Act. # | Schedule (Initial - Completion) |
|--|-----------------------|-----------------------|---|--------------------|--------------------|--------------|-----------------|-------------|---------------------------------|
| ① FITTINGS ON LAYERED PIPE INSULATION, Rm. 162, 167, 227, 459, 160 | N | Y | Rm-159, FITTINGS WERE REPLACED (CAN NOT FIND RM 160 OR 403) | Y | N | 5 | O+m | 8 | 8/7/98 to REMOVAL |
| ② GYMNASIUM FLEXIBLE CONCRETES (m) | N | N | N | N | N | 8 | O+m | 8 | 8/7/98 to REMOVAL |
| ③ LAYERED PAPER INSULATION, Rms 160, 162, 167, 227, + 159. | N | Y | Rm 159, LAYERED PIPE INSULATION WAS REPLACED W/ F.G. (CAN NOT FIND ROOM 160.) | Y | N | 5 | O+m | 8 | 8/7/98 to REMOVAL |

Key: **Classifications: Please See Attachment**

Homogenous Area

T - Thermal System Insulation
 S - Surfacing Material
 M - Miscellaneous

Response Action

RM - Remove O&M - Operations and Management
 RP - Repair ISL - Isolate
 ECP - Encapsulate

Homogenous Area Assessment Table

School: HAVRE DE GRACE HIGH

| Homogenous Area (#), Type of Material | Sampled 1994-95 (Y/N) | Friable 1994-95 (Y/N) | Changes 1998 (Y/N) | Friable 1998 (Y/N) | Sampled 1998 (Y/N) | AHERA Class. | Response Action | Res. Act. # | Schedule (Initial - Completion) |
|---------------------------------------|-----------------------|-----------------------|--|--------------------|--------------------|--------------|-----------------|-------------|---------------------------------|
| ⑩ Auditorium - Boiler GASKET (T) | N | Y | Auditorium Boiler GASKET DAMAGED ALL OTHER GASKET FAIR CONDITION | Y | N | 8 | Otm | 5 | 8/7/98 to Removal |
| ⑪ BOILER INTERIOR REFRACTORY | N | Y | DAMAGED EXPOSED REFRACTORY TOP FRONT OF Auditorium Boiler. | Y | N | 1 | REPAIR, Otm | 5 | 8/7/98 to Removal |
| | | | | | | | | | |

Key: **Classifications: Please See Attachment**

Homogenous Area

- T - Thermal System Insulation
- S - Surfacing Material
- M - Miscellaneous

Response Action

- RM - Remove
- RP - Repair
- ECP - Encapsulate
- O&M - Operations and Management
- ISL - Isolate

FRIABLE HOMOGENEOUS AREA-ASSESSMENT

Name of School HAVRE DE GRACE
Inspector B. SCHWARTZ

Date Aug. 7, 1998
Sample ID 1

Material Type: BOILER TANK INSUL. Location: BOILER ROOM
Area: 600 Sq.Ft. _____ Ln.Ft.

COMMENTS (OPTIONAL)

DURING THE INSPECTION, THE CONTRACTOR (ANI INC, BALTIMORE) WAS PREPPING THE BOILER ROOM TO BEGIN REMOVAL OF THE TANK INSULATION. THE CONTRACTOR REPORTED THAT HE WILL REMOVE ALL THE TANK INSULATION AND SEVEN EXISTING FITTINGS

TWO FITTINGS REPORTED IN POOR CONDITION WERE EASY REMOVED. HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

Physical
Significant _____
Moderate _____
None X

Water
Extensive _____
Moderate _____
Slight _____
None X

Deterioration
Heavy _____
Moderate _____
Light _____
None X

DISTURBANCE FACTORS

Proximity to Repair items
< 1ft. _____
1 to 5ft. N/A
Over 5ft. _____

Accessible
Within reach X
Barely _____
Unreachable _____

Texture
Rough X
Pitted _____
Moderate _____
Smooth _____

Adjacent Rooms
Gymnasium X
Music Rm. _____
Mech. Rm. _____
Elevators _____

AIR FLOW FACTORS

Barriers
Permanent _____
Enclosed _____
Encapsulated _____
None X

Ventilation
Yes X
No _____
If yes, intake _____
exhaust _____

Air Movement
High _____
Moderate _____
Low X

Air Conduits
Air plenum _____
Air shaft _____
Elevator X
Shaft _____

THE TANK INSULATION IS IN GOOD CONDITION. THE TANK IS BEING REPLACED BECAUSE OF LEAKS.

FRIABLE HOMOGENEOUS AREA-ASSESSMENT

Name of School HAVE DE GRACE

Date Aug 7, 1998

Inspector B. SCHMUTER

Sample ID 2

| | |
|--|-----------------------------------|
| Material Type: <u>FITTINGS ON F.G. LINES</u> | Location: <u>THROUGHOUT BLDG.</u> |
| Area: _____ Sq.Ft. | Ln.Ft. <u>250 EACH</u> |

COMMENTS (OPTIONAL)

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| |
|-------------------|
| Physical |
| Significant _____ |
| Moderate _____ |
| None <u>X</u> |

| |
|-----------------|
| Water |
| Extensive _____ |
| Moderate _____ |
| Slight _____ |
| None <u>X</u> |

| |
|----------------|
| Deterioration |
| Heavy _____ |
| Moderate _____ |
| Light _____ |
| None <u>X</u> |

DISTURBANCE FACTORS

| |
|---------------------------|
| Proximity to Repair items |
| < 1ft. _____ |
| 1 to 5ft. <u>N/A</u> |
| Over 5ft. _____ |

| |
|----------------------|
| Accessible |
| Within reach _____ |
| Barely _____ |
| Unreachable <u>X</u> |

| |
|-------------------|
| Texture |
| Rough _____ |
| Pitted _____ |
| Moderate <u>X</u> |
| Smooth _____ |

| |
|-----------------|
| Adjacent Rooms |
| Gymnasium _____ |
| Music Rm. _____ |
| Mech. Rm. _____ |
| Elevators _____ |

N/A

AIR FLOW FACTORS

| |
|--------------------|
| Barriers |
| Permanent _____ |
| Enclosed _____ |
| Encapsulated _____ |
| None <u>X</u> |

| |
|----------------------|
| Ventilation |
| Yes <u>X</u> |
| No _____ |
| If yes, intake _____ |
| exhaust _____ |

| |
|----------------|
| Air Movement |
| High _____ |
| Moderate _____ |
| Low <u>X</u> |

| |
|---------------------|
| Air Conduits |
| Air plenum <u>X</u> |
| Air shaft _____ |
| Elevator <u>X</u> |
| Shaft _____ |

FRIABLE HOMOGENEOUS AREA-ASSESSMENT

Page _____

Name of School HAVRE DE GRACE

Date Aug. 7, 1998

Inspector B. SCHMUTER

Sample ID 7

| | |
|--|--|
| Material Type: <u>FITTINGS ON LAYERED</u> | Location: <u>Room 162, 167, 227, 403</u> |
| Area: _____ Sq.Ft. _____ Ln.Ft. <u>50 EACH</u> | <u>PIPE INSULATION</u> |

COMMENTS (OPTIONAL)

Room 159 - FITTINGS WERE REPLACED - CAN NOT LOCATE
Room 403.

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| |
|-------------------|
| Physical |
| Significant _____ |
| Moderate _____ |
| None <u>X</u> |

| |
|-----------------|
| Water |
| Extensive _____ |
| Moderate _____ |
| Slight _____ |
| None <u>X</u> |

| |
|----------------------|
| Deterioration |
| Heavy _____ |
| Moderate _____ |
| Light _____ |
| None <u>X</u> |

DISTURBANCE FACTORS

| |
|----------------------------------|
| Proximity to Repair items |
| < 1ft. _____ |
| 1 to 5ft. <u>N/A</u> |
| Over 5ft. _____ |

| |
|----------------------|
| Accessible |
| Within reach _____ |
| Barely _____ |
| Unreachable <u>X</u> |

| |
|-------------------|
| Texture |
| Rough _____ |
| Pitted _____ |
| Moderate <u>X</u> |
| Smooth _____ |

| |
|-----------------------|
| Adjacent Rooms |
| Gymnasium _____ |
| Music Rm. _____ |
| Mech. Rm. _____ |
| Elevators _____ |

N/A

AIR FLOW FACTORS

| |
|--------------------|
| Barriers |
| Permanent _____ |
| Enclosed _____ |
| Encapsulated _____ |
| None <u>X</u> |

| |
|----------------------|
| Ventilation |
| Yes <u>X</u> |
| No _____ |
| If yes, intake _____ |
| exhaust _____ |

| |
|---------------------|
| Air Movement |
| High _____ |
| Moderate _____ |
| Low <u>X</u> |

| |
|---------------------|
| Air Conduits |
| Air plenum _____ |
| Air shaft _____ |
| Elevator <u>X</u> |
| Shaft _____ |

FRIABLE HOMOGENEOUS AREA-ASSESSMENT

Page _____

Name of School HAVRE DE GRACE

Date Aug 7, 1998

Inspector B. SCHMUTER

Sample ID 9

| | |
|---|--|
| Material Type: <u>LAYERED PIPE INSULATION</u> | Location: <u>Rms. 160, 162, 167, 227, 159.</u> |
| Area: _____ Sq.Ft. <u>150</u> | Ln.Ft. _____ |

COMMENTS (OPTIONAL)

Room 159 LAYERED PIPE INSULATION WAS REPLACED WITH FIBERGLASS. CAN NOT LOCATE ROOM 160

HAZARD ASSESSMENT FACTORS

DAMAGE FACTORS

| |
|-------------------|
| Physical |
| Significant _____ |
| Moderate _____ |
| None <u>X</u> |

| |
|-----------------|
| Water |
| Extensive _____ |
| Moderate _____ |
| Slight _____ |
| None <u>X</u> |

| |
|----------------------|
| Deterioration |
| Heavy _____ |
| Moderate _____ |
| Light _____ |
| None <u>X</u> |

DISTURBANCE FACTORS

| |
|----------------------------------|
| Proximity to Repair items |
| < 1ft. _____ |
| 1 to 5ft. _____ <u>N/A</u> |
| Over 5ft. _____ |

| |
|----------------------|
| Accessible |
| Within reach _____ |
| Barely _____ |
| Unreachable <u>X</u> |

| |
|-------------------|
| Texture |
| Rough _____ |
| Pitted _____ |
| Moderate <u>X</u> |
| Smooth _____ |

| |
|-----------------------|
| Adjacent Rooms |
| Gymnasium _____ |
| Music Rm. _____ |
| Mech. Rm. _____ |
| Elevators <u>X</u> |

N/A

AIR FLOW FACTORS

| |
|--------------------|
| Barriers |
| Permanent _____ |
| Enclosed _____ |
| Encapsulated _____ |
| None <u>X</u> |

| |
|----------------------|
| Ventilation |
| Yes <u>X</u> |
| No _____ |
| If yes, intake _____ |
| exhaust _____ |


| |
|---------------------|
| Air Movement |
| High _____ |
| Moderate _____ |
| Low <u>X</u> |

| |
|---------------------|
| Air Conduits |
| Air plenum <u>X</u> |
| Air shaft _____ |
| Elevator <u>X</u> |
| Shaft _____ |

5.0 LABORATORY RESULTS

There were no bulk samples taken at the subject facility.

6.0 CERTIFICATIONS



ManTech Environmental Corporation
1901 Research Blvd, Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

BRIAN J. HUG

has successfully completed an EPA approved course and examination for

AHERA Management Planner—16 Hours

and has completed training for accreditation under TSCA Title II

June 4-5, 1998

Location of Training: Rockville, MD

Certificate Number: 98-06-05-02

Certificate Expires: June 5, 1999

Exam Date: June 5, 1998

A handwritten signature in cursive script that reads "Alex Baylor".

Instructor: Alex Baylor


A handwritten signature in cursive script that reads "Rachel M. Riley".

Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation





ManTech Environmental Corporation
1901 Research Blvd., Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

BRIAN J. HUG

has successfully completed an EPA approved course and examination for

AHERA Building Inspector Refresher—4 Hours

and has completed training for accreditation under TSCA Title II

May 27, 1998

Location of Training: Rockville, MD

Certificate Number: 98-05-27-01

Certificate Expires: May 27, 1999

Exam Date: May 27, 1998

A handwritten signature in black ink, appearing to read "Daniel Bennett".

Instructor: Daniel Bennett, CET

A handwritten signature in black ink, appearing to read "Rachel M. Riley".

Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation



Printed on recycled paper



ManTech Environmental Corporation
1901 Research Blvd, Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

KAREN KARKUT

has successfully completed an EPA approved course and examination for

AHERA Building Inspector—24 Hours

and has completed training for accreditation under TSCA Title II


June 1-3, 1998


Location of Training: Rockville, MD

Certificate Number: 98-06-03-03

Certificate Expires: June 3, 1999

Exam Date: June 3, 1998


Instructor: Daniel Bennett, CET



Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation



Printed on recycled paper



ManTech Environmental Corporation
1901 Research Blvd., Suite 240 • Rockville, MD 20850
Phone: (301) 315-0080 • FAX: (301) 315-8188

This is to certify that

BETH SCHMUTER

has successfully completed an EPA approved course and examination for


AHERA Building Inspector Refresher—4 Hours

and has completed training for accreditation under TSCA Title II

August 10, 1998

Location of Training: Rockville, MD
Certificate Number: 98-08-10-09
Certificate Expires: August 10, 1999
Exam Date: August 10, 1998


Instructor: Rachel Riley, CET


Course Director: Rachel M. Riley, CET

This Course Meets the Maryland State Training Requirements (ManTech Approval #21-17-10).

A ManTech International Corporation



7.0 ATTACHMENTS

***(NOTE TO READER: SECTION 7.0 WAS
DELIVERED TO THE CLIENT UNDER A SEPARATE
COVER.)***

Limitations and Exclusions

All the professional opinions presented in this report are based solely on the scope of work conducted and sources referred to in our report. The data presented by Brook in this report was collected and analyzed using generally accepted industry methods and practices at the time the report was generated. This report represents the conditions, locations, and materials that were observed at the time the field work was conducted. No inferences regarding other conditions, locations, or materials, at a later or earlier time may be made based on the contents of the report. Brook's liability and that of its contractors and subcontractors, arising from any services rendered hereunder, shall not exceed the total fee paid by the client to Brook for this project. No other warranty, express or implied is made. The accuracy of this report is limited to the accuracy of the information obtained by Brook. This report was prepared for the sole use of our client. The use of this report by anyone other than our client or Brook is strictly prohibited without the expressed prior written consent of Brook. Portions of this report may not be used independent of the entire report.

EMSL Analytical, Inc.

10766 Rhode Island Ave
 Beltsville, MD 20705
 Phone: (301) 937-5700 Fax: (301) 937-5701



Attn.: William Burris/Jason Jacobs
 Brook Environmental & Engineering
 1322 Kingsbury Road
 Owing Mills, MD 21117

Thursday, September 24, 1998

Ref Number: MD981281

POLARIZED LIGHT MICROSCOPY (PLM)
 Performed by EPA 600/R-93/116 Method*

Project: Havre de Grace High - Harford County

| SAMPLE | LOCATION | APPEARANCE | SAMPLE TREATMENT | ASBESTOS | | NONASBESTOS | |
|--------|---------------------|--------------------------------------|------------------|----------|---------------|-------------|----------------------|
| | | | | % | TYPE | % | FIBROUS % NONFIBROUS |
| #01 | Havre de Grace High | Cream/Rust Fibrous Homogeneous | Teesed/Dissolved | 95% | Chrysotile | | 5% Other |
| #02 | Havre de Grace High | Cream/Grey Fibrous Homogeneous | Teesed/Dissolved | | None Detected | 20% | Glass 80% Other |
| #03 | Havre de Grace High | Grey Fibrous Homogeneous | Teesed/Dissolved | | None Detected | 25% | Glass 75% Other |

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

George P. Malone Jr.
 Analyst

Approved
 Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in part with written approval by EMSL. The above test must not be used by the client to obtain product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Analysis performed by EMSL Beltsville, MD. AIR and EHS. #200283. JAD/LLC. 01/000000

1322 KINGSBURY ROAD, OWINGS MILLS, MARYLAND 21117

CHAIN-OF-CUSTODY RECORD

P.O. #:

01/01/1994 22:56 3019375701 EMSL BELTSVILLE PAGE 08

CLIENT: HAIRE DE GRACE HIGH - HARFORD COUNTY
ADDRESS: 1322 Kingsbury Rd. OM, MD 21117
PHONE: (410) 356-4875 FAX: (410) 356-5073
CLIENT PROJECT #: 98-7-433 PROJECT MANAGER: BETH SCHMUTER

DATE: 9/21/98 PAGE _____ OF _____
TEG PROJECT #: _____
LOCATION: _____
COLLECTOR: B. SCHMUTER DATE OF COLLECTION: _____

| Sample Number | Depth | Time | Sample Type | Container Type | ANALYSES | | | | | | | | | | | | | | FIELD NOTES | Total Number of Containers | Laboratory Note Number | |
|-------------------------|-------|------|-------------|----------------|--------------|--------------|--------------|-------------------|-----------|----------------------|-----------------------|--------------|---------------|------------|--------------|------------|----|----------|-------------|----------------------------|------------------------|--|
| | | | | | VOA 801/8010 | VOA 802/8020 | VOA 804/8040 | Semi Vol 825/8270 | TPH 818.1 | TPH 8015 (Hexachlor) | TPH 8015 (Heptachlor) | PNA 610/8100 | PEST/PCB 8080 | HEX CHROME | ORGANIC LEAD | TOTAL LEAD | PH | ASBESTOS | | | | |
| HAIRE DE GRACE - RIG 01 | | | BULK | | | | | | | | | | | | | | | | | | | |
| HAIRE DE GRACE - RIG 02 | | | BULK | | | | | | | | | | | | | | | | | X | | |
| HAIRE DE GRACE - RIG 03 | | | BULK | | | | | | | | | | | | | | | | | X | | |
| | | | | | | | | | | | | | | | | | | | | X | | |
| | | | | | | | | | | | | | | | | | | | | | | |

DO NOT DO STOP (+)

| | | | |
|---|------------------------------|---|----------------------|
| RELINQUISHED BY (Signature) <i>Karen</i> | DATE/TIME 9/21/98 11:30AM | RECEIVED BY (Signature) <i>Beth Schmuter</i> | DATE/TIME 9/21/98 |
| RELINQUISHED BY (Signature) | DATE/TIME | RECEIVED BY (Signature) | DATE/TIME |

SAMPLE RECEIPT

TOTAL NUMBER OF CONTAINERS

CHAIN OF CUSTODY SEALS Y/N/A

SEALS INTACT? Y/N/A

RECEIVED GOOD COND./COLD

NOTES:

LABORATORY NOTES:

Per Karen S Day JAT

SAMPLE DISPOSAL INSTRUCTIONS

TEG DISPOSAL @ \$2.00 each Return Pickup

MEMORANDUM

TO: All Principals
FROM: Patti Jo Beard
SUBJECT: Reinspections for AHERA Compliance
DATE: July 28, 1995

The Asbestos Hazard Emergency Response Act (AHERA) requires all Local Education Agencies (LEA's) to complete inspections that identify asbestos containing materials (ACM) in all school buildings. Results of the inspection must then be compiled in a management plan to instruct building occupants, maintenance staff, parents, and any interest parties how to safely and effectively manage any asbestos identified during the inspection.

Following the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens, and McCoy conducted the initial inspection for Harford County Public Schools. In 1992, the first reinspection was completed by i-TEM, Ltd. This year's reinspection will be conducted by Testwell Craig Testing Laboratories, Inc.

The reinspections will involve visual inspection, taking samples of some building materials for analysis and updating current management plans. Any samples taken will be very small and the sample locations will be patched. The actual site work will require a few days at each building. Activities connected with the inspections will require contractor personnel to work in the school during the regular working day and some evening hours. Scheduling will require cooperation between school, contractor and Facilities Department personnel.

Site work will begin the first week of August and continue through the month. All documentation will be done by the first week of October. As the updated documents become available, you will receive the school's copy. Each site will be notified as the details in scheduling are finalized. Please inform building occupants of the upcoming activities. If there any questions, please do not hesitate to contact me.

slb

cc: Roger C. Niles
Jeffrey C. Ayers

LETTER OF ASSURANCE
THREE-YEAR REINSPECTION OF SCHOOL BUILDINGS PURSUANT TO AHERA

RESPONSIBLE GOVERNING AUTHORITY

| | | |
|--|--|---|
| Name of Responsible Governing Authority HARFORD COUNTY PUBLIC SCHOOLS | | Telephone Number (410) 838-7300 |
| Street Address 2209 CONOWINGO ROAD | | |
| Town BEL AIR, MARYLAND 21015 | | County HARFORD |
| Name of Asbestos Program Manager PATTI JO BEARD | Affiliation 2209 CONOWINGO ROAD, BEL AIR, MARYLAND 21015 | Telephone Number (410) 638-4204 |
| Name of Facility HAVRE DE GRACE HIGH SCHOOL | | Telephone Number (410) 939-6600 |
| Building Assessed HAVRE DE GRACE HIGH SCHOOL/MAIN BUILDING AND AUDITORIUM/GYM BUILDING | Asb. Mgt. Plan Number | |
| Street Address 700 CONGRESS AVENUE | | |
| Town HAVRE DE GRACE, MARYLAND 21078-3089 | | County HARFORD |
| Date Three-Year Reinspection Occurred AUG 08, 1995 | | |

INSPECTORS/ASSESSORS

| | | | |
|---|---|---|---|
| 1 | Name: WILLIAM THAW | Address: 5429 E. HARDING HIGHWAY MAYS LANDING, NJ 08330 | Telephone Number (609) 625-1700 |
| | Affiliation: TESTWELL CRAIG TESTING LABS., INC. | State of Accreditation/Acc. No. MD 12979 | Signature <i>W.E. Thaw</i> |
| 2 | Name: | Address | Telephone Number |
| | Affiliation | State of Accreditation/Acc. No. | Signature |
| 3 | Name | Address | Telephone Number |
| | Affiliation | State of Accreditation/Acc. No. | Signature |

GENERAL INFORMATION

Name of Facility: HAVRE DE GRACE HIGH SCHOOL

Building Assessed: HAVRE DE GRACE HIGH SCHOOL

Building Description:

HAVRE DE GRACE HIGH SCHOOL IS A 3 STORY BUILDING CONSTRUCTED IN 1955.
ADDITIONS WERE MADE IN 1958, 1971, 1976 AND 1984. NO RENOVATIONS WERE
MADE.

BUILDINGS INCLUDES: AUDITORIUM, 2 GYMNASIUMS & ADDITIONAL CLASSROOMS
IN A SEPARATE STRUCTURE ACROSS CONGRESS AVENUE FROM MAIN BUILDING.

Inspection Description:

THE HAVRE DE GRACE HIGH SCHOOL WAS INSPECTED ON AUGUST 8, 1995 BY
WILLIAM THAW OF TESTWELL CRAIG TESTING LABORATORIES, INC.

PREVIOUSLY DETERMINED ACBM IN BUILDINGS:

BOILER ROOMS TANK INSULATION 600 SQ FT, FITTINGS ON F/G INSULATED
PIPE, AUDITORIUM: STAGE LIGHT WIRING 212 LN FT, VIBRATION COLLARS 4,
GYMNASIUM: VIBRATION COLLARS ON AIR HANDLERS 8, GYM/AUDITORIUM:
BUILDING FIRE DOORS. THROUGHOUT REMAINDER OF SCHOOL: 9" X 9" VAT
600 SQ FT, 12" X 12" VAT 22,000, ASSOCIATED MASTIC 30,000 SQ FT,
FITTINGS ON F/G INSULATED PIPE, LAYERED PIPE INSULATION.

HAVRE DE GRACE HIGH SCHOOL

| | |
|--|--|
| GYM BUILDING BOILER ROOM | FITTING LEFT SIDE OF WATER TANK SEVERLY DAMAGED/FITTING ABOVE BOILER ROOM DOOR IN CORRIDOR DAMAGED |
| GYM BUILDING CORRIDOR | EXIT NEAR GIRLS DRESSING ROOM 2 CHIPPED 12" X 12" TILES |
| GYM BUILDING CORRIDOR AT PRACTICE ROOM 6 | 5 MISSING & 2 BROKEN 12" X 12" TILES |
| AUDITORIUM BOILER ROOM | HEATING SUPPLY EXPANSION TANK COVER BLISTERING |
| MAIN BUILDING BOILER RM #124 | TANK INSULATION SEPARATING ON END |
| MAIN BUILDING BOILER #1 | EXHAUST INSULATION 3" X 6" TEAR IN INSUL. |
| CORRIDOR OUTSIDE ROOM #139 | 5 DAMAGED 12" X 12" TILES |
| CORRIDOR #170 | 6 DAMAGED 12" X 3" TILES |
| NURSE OFFICE BOYS SIDE | ROOM 134 1 BROKEN 12" X 12" TILE EXPOSED MASTIC |
| ROOM #143 | 3 DAMAGED 12" X 12" NEAR TEACHERS DESK |
| ROOM #167 | 1 MISSING, 1 LOOSE, 1 BROKEN 9" X 9" UNDER SINK |
| ROOM #158 | 2 MISSING, 1 BROKEN 9" X 9" TILE |
| ROOM #204 | 2 BROKEN 12" X 12" TILES MASTIC EXPOSED |
| ROOM #201 | 5 CHIPPED 12" X 12" TILES |
| ROOM #306 | 3 DAMAGED 9" X 9" TILES |
| CORRIDOR #307 | 2 CRACKED 9" X 9" TILES NEAR ROOM #309 |
| ALL OTHER PREVIOUSLY DETERMINED ACBM | WAS FOUND TO BE IN GOOD CONDITION AT TIME OF INSPECTION |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| WILLIAM THAW TECHNICIAN NAME: | <i>W. E. Thaw</i> TECHNICIAN SIGNATURE |

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D1

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: GYM BUILDING CORRIDOR NEAR GIRLS DRESSING ROOM

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly (X) ACBM w/Potential for Damage
Damaged Thermal Systems Ins () ACBM w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACBM
Surfacing ACM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly () ACBM w/Potential for Damage
Damaged Thermal Systems Ins () ACBM w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACBM
Surfacing ACM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D2

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: GYM BUILDING CORRIDOR AT PRACTICE ROOM 6

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins (X) ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins () ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D3

Building Assessed: HAVRE DE GRACE HIGH
Room/Functional Space: CORRIDOR AT ROOM 139

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL
 (CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|--|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input checked="" type="checkbox"/> MISC |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input checked="" type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: _____ | <input type="checkbox"/> Other: _____ |

Homogeneous ID: _____ Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input checked="" type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

Response Actions _____ Date of Response _____ Sq/Ln Feet _____
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: **REPLACE OR REPAIR**

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL
 (CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|---------------------------------------|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input type="checkbox"/> MISC. |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: _____ | <input type="checkbox"/> Other: _____ |

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

Response Actions _____ Date of Response _____ Sq/Ln Feet _____

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D4

Building Assessed: **HAVRE DE GRACE HIGH**

Room/Functional Space: **CORRIDOR AT 170**

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|--|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input checked="" type="checkbox"/> MISC |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input checked="" type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: | <input type="checkbox"/> Other: |

Homogeneous ID: _____ Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input checked="" type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

| | | |
|---|------------------|------------|
| Response Actions | Date of Response | Sq/Ln Feet |
| MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995 | | |

COMMENTS: **REPLACE OR REPAIR**

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|-----------------------------------|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input type="checkbox"/> MISC. |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: | <input type="checkbox"/> Other: |

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

| | | |
|------------------|------------------|------------|
| Response Actions | Date of Response | Sq/Ln Feet |
|------------------|------------------|------------|

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D5

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: NURSE'S OFFICE BOYS SIDE

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly (X) ACM w/Potential for Damage
Damaged Thermal Systems Ins () ACM w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACM
Surfacing ACM or Friable Suspected ACM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly () ACM w/Potential for Damage
Damaged Thermal Systems Ins () ACM w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACM
Surfacing ACM or Friable Suspected ACM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D6

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 143

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly (X) ACMB w/Potential for Damage
Damaged Thermal Systems Ins () ACMB w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACMB
Surfacing ACM or Friable Suspected ACMB
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly () ACMB w/Potential for Damage
Damaged Thermal Systems Ins () ACMB w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACMB
Surfacing ACM or Friable Suspected ACMB
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D7

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 167

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|--|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input checked="" type="checkbox"/> MISC |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input checked="" type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: | <input type="checkbox"/> Other: |

Homogeneous ID: _____ Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input checked="" type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

| | | |
|---|------------------|------------|
| Response Actions | Date of Response | Sq/Ln Feet |
| MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995 | | |

COMMENTS: **REPLACE OR REPAIR**

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|-----------------------------------|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input type="checkbox"/> MISC. |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: | <input type="checkbox"/> Other: |

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

| | | |
|------------------|------------------|------------|
| Response Actions | Date of Response | Sq/Ln Feet |
|------------------|------------------|------------|

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D8

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 158

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins (X) ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins () ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D9

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 204

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|--|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input checked="" type="checkbox"/> MISC |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input checked="" type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: | <input type="checkbox"/> Other: |

Homogeneous ID: _____ Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input checked="" type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

Response Actions _____ Date of Response _____ Sq/Ln Feet _____
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

| | | |
|--|---|-----------------------------------|
| <input type="checkbox"/> THERMAL | <input type="checkbox"/> SURFACING | <input type="checkbox"/> MISC. |
| Check One: <input type="checkbox"/> Air Cell | <input type="checkbox"/> Ceiling <input type="checkbox"/> Spray-on | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Pipe Ins. | <input type="checkbox"/> Cementitious <input type="checkbox"/> Wall <input type="checkbox"/> Trowelled-on | <input type="checkbox"/> Ceiling |
| <input type="checkbox"/> Elbow/Joint | <input type="checkbox"/> Solid Lag <input type="checkbox"/> Other: <input type="checkbox"/> Other: | <input type="checkbox"/> Transite |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Other: | <input type="checkbox"/> Other: |

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
 Material: Friable Non-Friable Total Sq/Lf: _____
 Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage

| | |
|---|---|
| <input type="checkbox"/> Damage or <input type="checkbox"/> Significantly Damaged Thermal Systems Ins | <input type="checkbox"/> ACBM w/Potential for Damage |
| <input type="checkbox"/> Damaged Friable Surfacing ACM | <input type="checkbox"/> ACBM w/Potential for Significant Damage |
| <input type="checkbox"/> Significantly Damaged Friable Surfacing ACM | <input type="checkbox"/> Any Remaining Friable ACBM or Friable Suspected ACBM |
| <input type="checkbox"/> Damaged or <input type="checkbox"/> Significantly Damaged Friable Misc. ACM | |

Response Actions _____ Date of Response _____ Sq/Ln Feet _____

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D10

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 201

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins (X) ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins () ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D11

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 306

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins (X) ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly Damaged Thermal Systems Ins () ACBM w/Potential for Damage
() Damaged Friable Surfacing ACM () ACBM w/Potential for Significant Damage
() Significantly Damaged Friable Surfacing ACM () Any Remaining Friable ACBM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

ROOM/FUNCTIONAL SPACE INSPECTION-RESPONSE ACTIONS

D12

Building Assessed: HAVRE DE GRACE HIGH

Room/Functional Space: ROOM 307

SECTION I: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING (X) MISC
Check One: () Air Cell () Ceiling () Spray-on (X) VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: () Sample Taken (X) Material Assumed
Material: () Friable (X) Non-Friable Total Sq/Lf:
Material: (X) Localized () Distributed Accessibility: () 1 (X) 2 () 3

Degree of Damage
() Damage or () Significantly (X) ACBM w/Potential for Damage
Damaged Thermal Systems Ins () ACBM w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACBM
Surfacing ACM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet
MAINTAIN ON OPERATIONS & MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPLACE OR REPAIR

SECTION II: TYPE OF ASBESTOS-CONTAINING MATERIAL

(CHECK ONLY ONE TYPE PER SHEET)

() THERMAL () SURFACING () MISC.
Check One: () Air Cell () Ceiling () Spray-on () VAT
() Pipe Ins. () Cementitious () Wall () Trowelled-on () Ceiling
() Elbow/Joint () Solid Lag () Other: () Other: () Transite
() Other: () Other: () Other:

Homogeneous ID: Check One: () Sample Taken () Material Assumed
Material: () Friable () Non-Friable Total Sq/Lf:
Material: () Localized () Distributed Accessibility: () 1 () 2 () 3

Degree of Damage
() Damage or () Significantly () ACBM w/Potential for Damage
Damaged Thermal Systems Ins () ACBM w/Potential for
() Damaged Friable Surfacing ACM Significant Damage
() Significantly Damaged Friable () Any Remaining Friable ACBM
Surfacing ACM or Friable Suspected ACBM
() Damaged or () Significantly Damaged Friable Misc. ACM

Response Actions Date of Response Sq/Ln Feet

Building Assessed: HAVRE DE GRACE HIGH
Room/Functional Space: GYM BUILDING BOILER ROOM

SECTION I: TYPE OF ACM (CHECK ONLY ONE TYPE PER SHEET)

- THERMAL SURFACING MISC.
- Check One: Air Cell Ceiling Spray-on VAT
- Pipe Ins. Cementitious Wall Trowelled-on Transite
- Elbow/Joint Solid Lag Other: Other: Other:
- Boiler Asbestos Block _____
- Duct Other: _____
- Breeching _____
- Hot Water Tank _____

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
Material: Friable Non-Friable Total Sq/Lf: _____
Material: Localized Distributed Accessibility: 1 2 3

- Degree of Damage
- Damaged or Significantly Damaged Thermal Systems Ins ACBM w/Potential for Damage
 - Damaged Friable Surfacing ACM ACBM w/Potential for Significant Damage
 - Significantly Damaged Friable Surfacing ACM Any Remaining Friable ACBM or Friable Suspected ACBM
 - Damaged or Significantly Damaged Friable Misc. ACM

Response Action: _____ Date: _____ Sq/Ln Feet: _____

MAINTAIN ON OPERATIONS AND MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: **REMOVE OR REPAIR & ENCAPSULATE**

SECTION II: TYPE OF ACM (CHECK ONLY ONE TYPE PER SHEET)

- THERMAL SURFACING MISC.
- Check One: Air Cell Ceiling Spray-on VAT
- Pipe Ins. Cementitious Wall Trowelled-on Transite
- Elbow/Joint Solid Lag Other: Other: Other:
- Boiler Asbestos Block _____
- Duct Other: _____
- Breeching _____
- Hot Water Tank Other: _____

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
Material: Friable Non-Friable Total Sq/Lf: _____
Material: Localized Distributed Accessibility: 1 2 3

- Degree of Damage
- Damaged or Significantly Damaged Thermal Systems Ins ACBM w/Potential for Damage
 - Damaged Friable Surfacing ACM ACBM w/Potential for Significant Damage
 - Significantly Damaged Friable Surfacing ACM Any Remaining Friable ACBM or Friable Suspected ACBM
 - Damaged or Significantly Damaged Friable Misc. ACM

Response Action: _____ Date: _____ Sq/Ln Ft: _____

Building Assessed: HAVRE DE GRACE HIGH
Room/Functional Space: MAIN BUILDING BOILER ROOM 124

SECTION I: TYPE OF ACM (CHECK ONLY ONE TYPE PER SHEET)

THERMAL SURFACING MISC.
Check One: Air Cell Ceiling Spray-on VAT
 Pipe Ins. Cementitious Wall Trowelled-on Transite
 Elbow/Joint Solid Lag Other: Other: Other:
 Boiler Asbestos Block
 Duct Other:
 Breeching
 Hot Water Tank

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
Material: Friable Non-Friable Total Sq/Lf: _____
Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage
 Damaged or Significantly Damaged Thermal Systems Ins ACBM w/Potential for Damage
 Damaged Friable Surfacing ACM ACBM w/Potential for Significant Damage
 Significantly Damaged Friable Surfacing ACM Any Remaining Friable ACBM or Friable Suspected ACBM
 Damaged or Significantly Damaged Friable Misc. ACM

Response Action: _____ Date: _____ Sq/Ln Feet: _____

MAINTAIN ON OPERATIONS AND MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REPAIR AND ENCAPSULATE

SECTION II: TYPE OF ACM (CHECK ONLY ONE TYPE PER SHEET)

THERMAL SURFACING MISC.
Check One: Air Cell Ceiling Spray-on VAT
 Pipe Ins. Cementitious Wall Trowelled-on Transite
 Elbow/Joint Solid Lag Other: Other: Other:
 Boiler Asbestos Block
 Duct Other:
 Breeching CAL SIL
 Hot Water Tank Other: EXHAUST

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
Material: Friable Non-Friable Total Sq/Lf: _____
Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage
 Damaged or Significantly Damaged Thermal Systems Ins ACBM w/Potential for Damage
 Damaged Friable Surfacing ACM ACBM w/Potential for Significant Damage
 Significantly Damaged Friable Surfacing ACM Any Remaining Friable ACBM or Friable Suspected ACBM
 Damaged or Significantly Damaged Friable Misc. ACM

Response Action: _____ Date: _____ Sq/Ln Ft: _____

REPAIR AND ENCAPSULATE

Building Assessed: HAVRE DE GRACE HIGH
Room/Functional Space: AUDITORIUM BOILER ROOM

SECTION I: TYPE OF ACM (CHECK ONLY ONE TYPE PER SHEET)

THERMAL SURFACING MISC.
Check One: Air Cell Ceiling Spray-on VAT
 Pipe Ins. Cementitious Wall Trowelled-on Transite
 Elbow/Joint Solid Lag Other: Other: Other:
 Boiler Asbestos Block _____
 Duct Other: _____
 Breeching COVERING
 Hot Water Tank Other: EXPANSION TANK

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
Material: Friable Non-Friable Total Sq/Lf: _____
Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage
 Damaged or Significantly ACBM w/Potential for Damage
Damaged Thermal Systems Ins ACBM w/Potential for
 Damaged Friable Surfacing ACM Significant Damage
 Significantly Damaged Friable Any Remaining Friable ACBM
Surfacing ACM or Friable Suspected ACBM
 Damaged or Significantly
Damaged Friable Misc. ACM

Response Action: _____ Date: _____ Sq/Ln Feet: _____
MAINTAIN ON OPERATIONS AND MAINTENANCE PROGRAM-SEPT. 1, 1995

COMMENTS: REWRAP AND ENCAPSULATE


SECTION II: TYPE OF ACM (CHECK ONLY ONE TYPE PER SHEET)

THERMAL SURFACING MISC.
Check One: Air Cell Ceiling Spray-on VAT
 Pipe Ins. Cementitious Wall Trowelled-on Transite
 Elbow/Joint Solid Lag Other: Other: Other:
 Boiler Asbestos Block _____
 Duct Other: _____
 Breeching _____
 Hot Water Tank Other: _____

Homogeneous ID: _____ Check One: Sample Taken Material Assumed
Material: Friable Non-Friable Total Sq/Lf: _____
Material: Localized Distributed Accessibility: 1 2 3

Degree of Damage
 Damaged or Significantly ACBM w/Potential for Damage
Damaged Thermal Systems Ins ACBM w/Potential for
 Damaged Friable Surfacing ACM Significant Damage
 Significantly Damaged Friable Any Remaining Friable ACBM
Surfacing ACM or Friable Suspected ACBM
 Damaged or Significantly
Damaged Friable Misc. ACM

Response Action: _____ Date: _____ Sq/Ln Ft: _____



CERTIFICATE NUMBER: 12979

THIS IS TO CERTIFY THAT

William E. Thaw

**HAS MET THE ATTENDANCE REQUIREMENTS
AND SUCCESSFULLY COMPLETED THE EXAM
IN THE COURSE ENTITLED**

ASBESTOS BUILDING INSPECTOR

EPA APPROVED COURSE UNDER TITLE II RULE

Environmental Training, Inc.
TRAINING PROVIDER

January 30 - February 1, 1995
COURSE DATE

1702 Industrial Highway, Suite 7
ADDRESS

February 1, 1996
EXPIRATION DATE

31-90-01-BI
COURSE APPROVAL NUMBER

William E. Thaw
STUDENT'S SIGNATURE

William Harcourt
COURSE DIRECTOR (NAME AND SIGNATURE)

STATE OF MARYLAND

REG # 007612



AHERA/EPA Accredited
Per 40 CFR Part 763

Certificate of Completion


This is to certify that John J. Gordon S/S #173-28-0758

has successfully completed the course entitled EPA/AHERA/N.Y. State 1/2 Day
Management Planner Refresher

on December 2, 19 94

Examination passed on N/A 19

Expiration date: Dec. 2, 1995


Doris L. Adler
President

Dec. 2, 1994
Date

3321 Doris Avenue, Building B, Ocean, NJ 07712 (908) 531-5571

TO: All Principals
FROM: Patti Jo Waddell
SUBJECT: Reinspection for AHERA Compliance
DATE: March 27, 1992

The Asbestos Hazard Emergency Response Act (AHERA) requires that all Local Education Agencies (LEAs) complete inspections to identify asbestos containing materials (ACM) in all school buildings and prepare management plans to safely and effectively manage any asbestos identified during the inspection. After the initial inspection, the LEA is required to conduct reinspections at least once every three years. Spotts, Stevens and McCoy conducted the initial inspection for Harford County Public Schools. All reinspections for HCPS will be done by i-TEM Limited, an environmental firm.

The reinspections will involve visual inspection, taking samples of some building materials for analysis and updating current management plans. Any samples taken will be very small and the sample locations will be patched. The actual site work will only be a couple days at each school. Activities connected with the inspections may require contractor personnel to work in the school during class hours. However, every effort will be made to schedule work outside normal class hours. Scheduling will require cooperation between school, contractor and Facilities department personnel.

The reinspections will begin the first week of April and continue through June. All documentation will be done by the first week of July. As the updated documents become available, you will receive the school's copy. You will be notified as the details in scheduling are finalized. Please inform staff, students and parents of upcoming activities. An example would be "According to AHERA requirements, all schools were inspected for asbestos in 1989 and a management plan was developed. Reinspections are required once every three years. This will be done during the spring of 1992 in all Harford County Public Schools. This information is provided in compliance with AHERA regulations." If there are any questions, please do not hesitate to contact me.

bm

pc: Roger C. Niles
Joseph M. Devilbiss

**AHERA Three (3) Year Reinspection Form
AHERA Management Plan Update**

This form is to be included in the Record Keeping section of the LEA- designee copy of each school's Management Plan. A copy of this form should also be kept in the corresponding school's copy of the Management Plan.

FACILITY: Havre de Grace High School

ADDRESS: 700 Congress Ave. Havre de Grace, MD 21078-3089

DATE: 4/15/92

EPA ACCRED. INSPECTOR: Heppner/Watson
(print)

SIGNATURE: Jamie H. Watson
(sign)

PREVIOUSLY IDENTIFIED AND/OR ASSUMED ACM:

| | |
|---|--|
| <u>Boiler Room (412)</u> | <u>Throughout the Building</u> |
| <u>Tank Insulation - 600 S.F.</u> | <u>Fittings on F/G Insul. Pipe 250 EA.</u> |
| | <u>9"x9" Floor Tile - 600 S.F.</u> |
| <u>Auditorium</u> | <u>1'x1' Floor Tile - 22,000 S.F.</u> |
| <u>Stage Light Wire Insulation - 212 L.F.</u> | <u>Floor Tile Mastic - 30,000 S.F.</u> |
| <u>Rooms 162,167,227, and 403</u> | |
| <u>Fittings on Layered Paper Pipe Insulation - 50 EA.</u> | |

CHANGES IN MATERIAL CONDITION:

Three (3) damaged fittings identified in Room 403

ADDITIONAL COMMENTS/ABATEMENT PROJECTS:

None

NEWLY IDENTIFIED/SAMPLED MATERIALS:

Assumed ACM flexible connectors in the gymnasium, however inaccessible for sampling.
Rooms 160, 162, 167, 227, and 159 have layered paper insulation which was previously sampled and determined to be non-asbestos containing in the SSM report. However our sample of this material (sample 001) was determined to be positive for asbestos content.

**AHERA Three (3) Year Reinspection Form
AHERA Management Plan Update**

FACILITY: Havre de Grace High School
ADDRESS: 700 Congress Ave. Havre de Grace, MD 21078-3089
DATE: 4/15/92

REMAINING ACM IN BUILDING:

Boiler Room (412)
Tank Insulation - 600 S.F.

Auditorium
Stage light Wire Insulation - 212 L.F.

Throughout School
Fittings On F/G Insulated Pipe - 250 EA.
9"x9" Floor Tile - 600 S.F.
1'x1' Floor Tile - 22,000 S.F.
Floor Tile Mastic - 30,000 S.F.

Rooms 162, 167, 227, 160, and 159
Fittings on Layered Paper Pipe Insulation - 75 EA. (increased from 50)
Layered Paper Pipe insulation - 150 L.F.

Gymnasium
Flexible Connectors - 12 S.F.

**AHERA Three (3) Year Reinspection Form
AHERA Management Plan Update**

FACILITY: Havre de Grace High School
ADDRESS: 700 Congress Ave. Havre de Grace, MD 21078-3089
DATE: 4/15/92

REMAINING ACM IN BUILDING:

~~Boiler Room (412) *Removed 8/98*~~
~~Tank Insulation - 600 S.F.~~

~~Auditorium~~
~~Stage light Wire Insulation - 212 L.F.~~

~~Throughout School~~
~~Fittings On F/G Insulated Pipe - 250 EA.~~
~~9"x9" Floor Tile - 600 S.F.~~
~~1'x1' Floor Tile - 22,000 S.F.~~
~~Floor Tile Mastic - 30,000 S.F.~~

~~*Fire doors (aud. bldg at least)*~~
~~Rooms 162, 167, 227, 160, and 159~~
~~Fittings on Layered Paper Pipe Insulation - 75 EA. (increased from 50)~~
~~Layered Paper Pipe insulation - 150 L.F.~~

~~Gymnasium~~
~~Flexible Connectors - 12 S.F.~~

2/97 - Fittings removed from girls bathroom foyer
8/98 - Tank and pipe insulation removed from gym boiler room.
6/02 - Removal of fittings in gym by girls lockerroom & bathroom

SAMPLE TRACKING SHEET

*CLIENT: Harford County Schools

Log # _____
Range: 5850 to _____

Howe De Grove HS

*PROJECT # 92.31.01.01

RECEIVENG

*Number of Samples: 1

*Analysis Required: PLM

*Turn-Around-Time:

Standard-- Rush. Emergency-- On-site

Date Received: 5/15/92

Received By: AB

LOGIN:

Log-in Date: 5/16/92

ANALYSIS:

Assigned To: AB

Analysis Started: 5/16/92

Completion Date: 5/16/92

QUALITY CONTROL

Q.C. Analyst(s): _____

No. of Q.C. Samples: 0

Date Q.C.'ed: 5/16/92

STORAGE:

Date Stored: 5/16/92

Stored By: AB

VERBAL RESULTS

*Contact: _____

*Phone Number: _____

Date Reported: 5/16/92

Reported By: _____

FINAL RESULTS

Data Entered (Y/N): 4

Entered By: AB

Date Entered: 5/27/92

PRINTED REPORT

Date Printed: 5/27/92

Proofed BY/Date: 1/1

Corrections Done: 1/1

Reprints: 1/1

APPROVED BY

AB 5/16/92

Signature

Date

Copied: 1/1

Mailed: 1/1

Accounting Print-out:

* To be completed by Field Personnel

i-T.E.M., Ltd.
5300 Westview Drive, Suite 404
Frederick, MD 21701

AIHA # 416
ELAP # 10882

LABORATORY ANALYTICAL REPORT
BULK ASBESTOS SAMPLE

CLIENT: Harford County Public Schools

ADDRESS: Hickory Annex-Facilities, US Route #1
Bel Air, MD 21014

JOB SITE: Harve De Grace High School

PROJECT NUMBER: P92-31.01.01

DATE COLLECTED: 5/15/92

DATE RECEIVED: 5/15/92

DATE ANALYZED: 5/16/92

LOCATION: Room 167; drafting room; paper wrap; pipe insulation

FIELD SAMPLE NUMBER: HAJR-50-001

LAB NUMBER: 92-005850

PHOTO #: N/P

GROSS DESCRIPTION: Tan/Orange, Fibrous, Heterogeneous

| ASBESTOS | | NON-ASBESTOS FIBROUS | |
|-------------------------|---------|--------------------------|---------|
| TYPE (s) | PERCENT | TYPE (s) | PERCENT |
| 1: Chrysotile | 05-10 | 1: Cellulose | 85-90 |
| 2: | | 2: | |
| 3: | | 3: | |
| TOTAL PERCENT ASBESTOS: | 05-10 % | NON-ASBESTOS/NON-FIBROUS | |
| | | TYPE | PERCENT |
| | | 1: Binding Material | 01-05 |

COMMENTS:

Accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP # 1003) for the analysis of asbestos bulk samples. Samples are analyzed using Polarized Light Microscopy (PLM) and Dispersion Staining Techniques (1% limit of detection). The results provided are visual estimates of composition and not actual "weight" percentages and relate only to the samples received by i-T.E.M., Ltd.

LABORATORY DIRECTOR: Jorge G. Rangel, Jr.
ASBESTOS ANALYST: Alece Bowman

DATE: 5/16/92





Aerosol Monitoring & Analysis, Inc.

This is to certify that

LONNIE WATSON

Social Security No. 575-96-3759

has successfully completed a(n)
8 hour training course entitled

E.P.A. INSPECTOR RECERTIFICATION PROGRAM

on

OCTOBER 11, 1991



Location HANOVER, MARYLAND

Certificate No. 91-1775

Expires OCTOBER 11, 1992

Training Division
1341 Ashton Road, Suite A
Hanover, MD 21076

301-684-3327
800-221-1745


Director of Training

Student



Aerosol Monitoring & Analysis, Inc.

This is to certify that

PETE HEPPNER

Social Security #: 219-68-2973

has successfully completed a(n)
8 hour training course entitled

E.P.A. INSPECTOR - MANAGEMENT PLANNER RECERTIFICATION PROGRAM

Presented by Aerosol Monitoring & Analysis, Inc.

on JULY 18, 1991

Location HANOVER, MARYLAND

Expires JULY 18, 1992

Training Division
1341 Ashton Road, Suite A
Hanover, MD 21076

Certificate # 91-1190

Steven E. Blizard

Director of Training

[Signature]
General Manager